8. Exposure controls/personal protection

Occupational exposure limits

The following constituents are the only constituents of the product which have a PEL, TLV or other recommended exposure limit. At this time, the other constituents have no known exposure limits.

Components	Type	Value	
Ammonia, aqueous solution (CAS 1336-21-6)	PEL	35 mg/m3	
		50 ppm	
US. ACGIH Threshold Limit Values	5		
Components	Туре	Value	Form
Ammonia, aqueous solution (CAS 1336-21-6)	STEL	35 ppm	
	TWA	25 ppm	
ETHYLENE GLYCOL (CAS 107-21-1)	STEL	10 mg/m3	Aerosol, inhalable.
		50 ppm	Vapor fraction
	TWA	25 ppm	Vapor fraction
NATURAL RUBBERS (CAS 9006-04-6)	TWA	0.0001 mg/m3	Inhalable fraction.
US. NIOSH: Pocket Guide to Chem	nical Hazards		
Components	Туре	Value	
Ammonia, aqueous solution (CAS 1336-21-6)	STEL	27 mg/m3	
		35 ppm	
	TWA	18 mg/m3	
		25 ppm	
US. Workplace Environmental Exp	oosure Level (WEEL) Guides		
Components	Type	Value	Form

Biological limit values

Propane-1,2-diol (CAS

No biological exposure limits noted for the ingredient(s).

Exposure guidelines

57-55-6)

US ACGIH Threshold Limit Values: Skin designation

NATURAL RUBBERS (CAS 9006-04-6)

Can be absorbed through the skin.

10 mg/m3

Aerosol.

Appropriate engineering

controls

Use adequate ventilation to control airborne concentrations below the exposure limits/guidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local

exhaust ventilation, or other engineering controls to control airborne levels below the

recommended exposure limits/guidelines.

TWA

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Hand protection Suitable chemical protective gloves should be worn when the potential exists for skin exposure.

The choice of an appropriate glove does not only depend on its material but also on other quality

features and is different from one producer to the other. Nitrile or neoprene gloves are

recommended.

Other Wear appropriate chemical resistant clothing if applicable.

Respiratory protection If engineering controls do not maintain airborne concentrations to a level which is adequate to

protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection

Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

FIR No.: 178617 SDS US

Issue Date: 05-30-2019

Version: 01