NIOSH. Immediately Dangerous to Life or Health (IDLH) Values, as amended

ComponentsTypeValueNAPHTHALENE (CAS 91-20-3)IDLH 0.9 %

250 ppm

US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL)

 Components
 Type
 Value

 Kerosine (petroleum) (CAS 8008-20-6)
 TWA
 100 mg/m3

 NAPHTHALENE (CAS 91-20-3)
 STEL
 75 mg/m3

 15 ppm
 TWA
 50 mg/m3 10 ppm

Biological limit values No biological exposure limits noted for the ingredient(s).

Exposure guidelines

US - California OELs: Skin designation

NAPHTHALENE (CAS 91-20-3) Can be absorbed through the skin.

US ACGIH Threshold Limit Values: Skin designation

Kerosine (petroleum) (CAS 8008-20-6)

NAPHTHALENE (CAS 91-20-3)

Danger of cutaneous absorption

Danger of cutaneous absorption

Appropriate engineering controls

Provide eyewash station and safety shower. Use adequate ventilation to control airborne concentrations below the exposure limits/guidelines. If user operations generate a vapor, dust and/or mist, use process enclosure, appropriate local exhaust ventilation, or other engineering controls to control airborne levels below the recommended exposure limits/guidelines.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Hand protection Suitable chemical protective gloves should be worn when the potential exists for skin exposure.

The choice of an appropriate glove does not only depend on its material but also on other quality features and is different from one producer to the other. Use protective gloves made of: Polyvinyl

chloride (PVC).

Other Wear appropriate chemical resistant clothing if applicable.

Respiratory protectionIf engineering controls do not maintain airborne concentrations to a level which is adequate to

protect worker health, an approved respirator must be worn. Respirator selection, use and maintenance should be in accordance with the requirements of OSHA Respiratory Protection

Standard 29 CFR 1910.134 and/or Canadian Standard CSA Z94.4.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

Observe any medical surveillance requirements. When using do not smoke. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove

anning, and/or smoking. Roddinory wash work dodning and protective equipment to remo

contaminants.

9. Physical and chemical properties

Appearance

Physical stateLiquid.FormLiquid.

Color CLEAR LIGHT YELLOW

Odor Not available.
Odor threshold Not available.
pH Not available.
Melting point/freezing point Not available.
Initial boiling point and boiling Not available.

range

Version: 01

Flash point 126.0 °F (52.2 °C)

FIR No.: 151786 SDS US

4/9