Contact product manufacturer for latest (M)SDS

ISSUED DATE: Aug. 27, 2015
REVISED DATE: Jul. 23, 2018

monoxide) may be generated by thermal decomposition or

combustion. Extinguish the fire form the windward.

6. ACCIDENTAL RELEASE MEASURES

Personal precautions : Keep personnel away except for authorized ones from spillage area

by stretching ropes. Wear proper equipment and avoid contact with skin and inhalation. Do not absorb/collect the spill downwind.

Environmental precautions : Prevent spills from entering sewers, watercourses or lower area

and prevent from affecting environent. Absorb or collect the spill

according to the disposal rules.

Methods and materials for contaminant and cleaning up

: Collect it using a vacuum cleaner or dust collection equipment. Absorb or collect the spill according to the disposal rules.

7. HANDLING AND STORAGE

Handling • Remove dust on work clothing using dust collection equipment etc.

· Wash mouth and hands etc. after handling.

· Use proper dust collection equipment to prevent dust from scattering.

· Avoid prolonged or frequently repeated exposure.

· Pregnant women must avoid exposure.

Storage

· Store in a dry place.

· Keep away from heat, steam pipe and sunlight.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Exposure control: Use adequate general or local exhaust ventilation to keep airborne concentrations below the permissible exposure limits. Facilities storing or utilizing these materials should be equipped with an eyewash and a safety shower.

Install a measuring instrument and a detector for flammable gases, toxic gases, if necessary.

Chemical name	OSHA PEL	ACGIH TLV
		TWA
Graphite	$15\text{mg/m}^3 \text{ (T)}$ $5\text{mg/m}^3 \text{ (R)}$	$2mg/m^3$ (R)
Zirconium oxide	5mg(Zr)/m ³	$5mg(Zr)/m^3$
		10mg(Zr)/m³ (STEL)
Copper	1mg/m³ (Dust and mists (as Cu))	1mg/m³ (Dust and mists (as Cu))
Aluminum oxide	5mg/m^3	$1\mathrm{mg/m^3}$
Barium sulfate	15mg/m^3 (T)	5mg/m^3 (T)
	5mg/m^3 (R)	
Calcium hydroxide	15mg/m^3 (T)	5mg/m^3 (T)
	5mg/m^3 (R)	

TLV: Threshold limit value, TWA: Time weighed average, (T): Total dust, (R): Respirable fraction (STEL): Short term exposure limit, (Zr): As elements

Personal protection equipment: Dust mask, Resistant gloves (e.g., nitrile glove), Safety goggles.