#### MATERIAL SAFETY DATA SHEET

corrosive gas within in a temperature range of -20 to 35°C. A temperature of 60°C or higher will accelerate the deterioration of battery performance.

# 8. Exposure Controls/Personal Protection

## **Engineering controls**

Keep away from heat and open flame. Store in a cool dry place.

### **Personal Protection**

### Respirator

Not required during normal operations. SCBA required in the event of a fire.

#### Eye/face protection

Not required beyond safety practices of employer.

### Gloves

Not required for handling of cells.

### Foot protection

Steel toed shoes recommended for large container handling.

# 9. Physical and Chemical Properties

State	Solid
Odor	N/A
PH	N/A
Vapor pressure	N/A
Vapor density	N/A
Boiling point	N/A
Solubility in water	Insoluble
Specific gravity	N/A
Density	N/A