Tox no.: 177936 Last Reviewed (C2 Status): 14/Aug/2006

FORM NO. : YMU-8544-003

ISSUE DATE: 7/4/2006

PAGE : 1/4

MATERIAL SAFETY DATA SHEET

1 CHEMICAL PRODUCT & COMPANY IDENTIFICATION

CHEMICAL PRODUCT NAME : FD10CG(ARTICLE)

NAME OF MANUFACTURER : Hitachi Chemical Company Ltd.(Yamazaki Works) ADDRESS : •3-3-1 Ayukawa-cho, Hitachi, Ibaraki, Japan

NAME OF SECTION : Automotive Products Division.

Friction Material Development Dept. Mr. S. Kudou

TELEPHONE NUMBER : •+81-294-38-6066 (Japan) FAX NUMBER : •+81-294-37-3621 (Japan)

EMERGENCY CALL : •MSI(Marubeni Specialty Chemicals, Inc.) [Business hours]

(Tel. +1-914-428-6317)

•CHEMTREC (Tel.+1-800-424-9300) [24 hours]

•Hitachi Chemical Company Ltd. Yamazaki works(Sakuragawa)

Tel. +81-294-38-6065(Japan)

FOR OTHER INFORMATION : +81-294-38-6066 (Japan)

2 COMPOSITION/INFORMATION ON INGREDIENTS

SUBSTANCE/MIXTURE :SOLID(ARTICLE)
INGREDIENTS AND COMPOSITION :

CHEMICAL NAME	COMPOSITION	CHEMICAL	CAS No.
	(Wt%)	FORMULA	
Cured Phenolic resin	5 - 12	<u>-</u>	(Trade Secret)
Cured cashew resin	2 - 10	<u>-</u>	(Trade Secret)
Copper	13 - 25	Cu	7440-50-8
Graphite	1 - 8	С	7782-42-5
Barium sulfate	15 - 30	BaSO₄	7727-43-7
Alumina (non-fibrous)	0.1 - 1	<u>-</u>	1344-28-1
Aramid fiber	1 - 6	<u>-</u>	26125-61-1
Mineral fiber	3 - 15	-	(Trade Secret)
Potassium titanate (flake)	10 - 22	K ₂ O•6TiO ₂	12056-51-8
Zirconium Oxide	10 - 20	ZrO2	1314-23-4
Antimony trisulfide	1 - 6	$Sb_{\!\scriptscriptstyle 2}\!S_{\!\scriptscriptstyle 3}$	1345-04-6

UN CLASS: Not Applicable
UN NUMBER: Not Applicable

3 HAZARDS IDENTIFICATION

CLASS NAME OF HAZARDOUS CHEMICALS: Not Applicable

PHYSICAL AND CHEMICAL HAZARDS : Cashew resin may cause allergic reaction with skin contact.

Dust from debris could pose inhalation hazard if misused.

ADVERSE HUMAN HEALTH EFFECTS: Not Available
ENVIRONMENTAL EFFECTS: Not Available

FD10CG YMU-8544-003

Tox no.: 177936 Last Reviewed (C2 Status): 14/Aug/2006