3.	Composition/Component Data	
	Name	CAS Number EINECS Number %
	Name	CAS Number EINECS Number %
	No Hazardous or Reportable Ingredients	
4.	First Aid Measures	
	Eye Contact	Check for and remove any contact lenses. Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting the upper and lower eyelids. Get medical attention if symptoms occur.
	Skin Contact	In case of contact, immediately flush skin with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Wash clothing before reuse. Get medical attention if symptoms occur.
	Inhalation	Move exposed person to fresh air. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. Loosen tight clothing such as a collar, tie, belt, or waistband. Get medical attention if symptoms occur.
	Ingestion	Wash out mouth with water. Do not induce vomiting unless directed to do so my medical personnel. Never give anything by mouth to an unconscious person. Get medical attention if symptoms occur.
	Protection for first-aiders	No action shall be taken involving any personal risk or without suitable training.
	Note to Physician	No specific treatment. Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
5.	Firefighting Measures	
J.	Suitable Extinguishing Media	Dry Chemical, CO _{2.} Foam. or Water Fog
	Special Exposure Hazards	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
	Hazardous thermal decomposition products	Burning may produce carbon monoxide, carbon dioxide, formaldehyde, as well as small amounts of other toxic fumes.
	Special protective equipment for firefighters	Fire-fighters should wear protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.
6.	Accidental Release Measures	
U.	Personal Precautions	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Put on appropriate personal protection equipment (see Section 8).
	Environmental Precautions	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains, and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil, or air).