GEP GoPro Hero 8 Naked



USER MANUAL

Summary	1
Features	
Specification	
Indicator status	
BEC Board Diagram & Set Guide	
Recording with transmitter	5
Wire Diagram	7
Turn on WiFi and connect APP	8
Connect:	9

Summary

GoPro hero 8 Naked, specially designed by GEP team for quadcopter, finally meets you. The newly designed BEC is perfect for GoPro 8. Support 2-6s voltage input and output 5V@2A. It is equipped with POWER/MODE and REC button, and has a quick detachable GH1.25-3P connector to support remote control.

Features

- 1. It's specially designed for quadcopter, and its ultra light weight is only 25.7g
- 2. 4K@60fps,4K@30fps,2.7K@50fps Recording
- 3. Scan preset QR code switch settings
- 4. BEC board input voltage 2S-6S,output5V-2A
- 5. Integrated GoPro POWER/MODE button and REC button, operation quickly and conveniently.
- 6. GH1.25-3P connector is used to connect flight control and realize remote control
- 7. UV protection lens to protect the camera
- 8. Nd16 filter to reduce the light input of camera sensor

Specification

Model: Naked GoPro Hero 8 Camera

Dimension: 60*40*22.5mm

Weight: 25.7g Input: 2-6S Output: 5V2A Memory: SD Card

Connector: GH 1.25 3PIN


Indicator status

Connect GH1.25 Control cable with camera and input 2-6s power.LED will flash 1 times,BEC plate power light is always on $(green \ light)$.

Instructions	Operation	Indicator
	Press the power/mode	Flash 3 times, off
Power on	switch once	ridding times, on
	Press and hold the power/	Flash 7 times, off
Power off	mode switch for 5 seconds	riasir / times, on
Start recording	Press the record switch once	Flash slowly
Stop recording	Press the record switch once	Flash 3 times, off
	Press the power/mode	
Switch mode	switch once	NONE
QR code switching recording		Flash 2 times, off
settings	Scan preset QR code	riasii 2 tiiiles, Oli




GoPro Hero 8 Naked Manual






Born For FPV

BEC Board Diagram & Set Guide



3/7





Born For FPV



●Install the camera on the front shell and fix it with an M1. 4*4 screw



QApply 3M double-side adhesive tape on the front shell.



Install the front screen and stick EVA insulation cotton on the back



4 Install GoPro Hero 8 Naked motherboard



⑤Install the BEC board , first connect the BEC, then connect POWER and MODE.



GConnect the BTB interface of camera and front screen



stick the EVA insulation cotton on BEC board



③Use M1.4*4 and M1.4*6 screws to fix the motherboard and BEC board




9Use M1. 4*8 screws to install the back shell

GEPRC

Born For FPV

Recording with transmitter

- 1. Weld control cable to FC(F411-AIO)
 - RED wire → positive pole
 - BLACK wire → negative pole
 - YELLOW wire→LED




Connect FC to BETAFLIGHT, enter the following command on the command wire, save.

```
resource LED_STRIP 1 NONE
resource PINIO 1 A08
set pinio_box = 40,255,255,255
Save
```

3. Turn on the USER1 mode under the mode option,add range to Transmitter idke switch.



4. Turn the BEC power switch to left, connect the control cable.





5. Supply power to FC,GoPro8 Naked will auto start. Operation remote control AUX4 switch, move the cursor from the white area to the yellow area and back to the white area to start the recording. Repeat the operation again to end the recording.



Notes: GEPRC-F722-AIO and F411-AIO have the same wiring but different codes, as follows:

resource LED_STRIP 1 NONE

resource PINIO 1 A01


set pinio_box = 40,255,255,255

Save



Wire Diagram

BEC board retains the welding pad, so you can by wiring to connect the camera main board. There is the wiring diagram:





Turn on WiFi and connect APP

- 1. Open GoPro Quick APP, and search camera .
- 2. Turn on Naked GoPro Hero8 And scan the QR code below, The red indicator will flash twice, and then press the video button three times, the Naked GoPro Hero 8 will enter the connection state.
- 3. Connect the WiFi of Naked GoPro Hero 8 according to the prompt of GoPro quick app.





Connect:

Website: https://geprc.com/

