Greenville Tube Material Safety Data Sheet

I. MATERIAL IDENTITY

MANUFACTURER'S NAME AND ADDRESS

Greenville Tube, P.O. Box 30, Greenville, PA 16125-0030 / Mill Address: P.O. Box 550, Clarksville, AR 72830

Phone Number:

724-588-6300

479-754-6500

Product Name/Trade Name

Chemical Name & Synonyms

Stainless Steel Tubing and/ Pipe

II. GENERIC INGR Base Metal: Alloys:	Iron Manganese Phosphorous Sulphur Silicon Chromium Nickel Columbium Copper Aluminum Titanium	7704-34-9 7740-21-3 7740-47-3 7740-02-0 7440-25-7 7440-50-8 7429-90-5 7439-98-7	% wt. 50-82 13.5 max 0.05 max 0.04 max 2.5 max 10-30 34.0 max 1.0 max 0.75 max 1.5 max 2.5 max	Permissible Exposure Limits PEL as Iron Oxide Fume PEL (c) as Manganese PEL as Phosphorous (Yellow) PEL as Sulfur Dioxide None Listed PEL Soluable Chromic/ Chromous Salts Chrome and Insoluable Salts PEL as Nickel Total dust PEL as Copper None Listed None Listed None Listed PEL as Mo PEL insoluble Mo PEL as Cobalt	Units 10 mg/M ³ 5 mg/M ³ 0.1 mg/M ³ 13 mg/M ³ 0.5 mg/M ³ 1 mg/M ³ 15 mg/M ³ 0:2 mg/M ³	10 mg/M³ 2. Vapor Pressure: NA 5 mg/M³ 3. Vapor Density: NA 4. Solubility in Water: NA 13 mg/M³ 5. Specific Gravity: 7. 6. % Volatile by Volume: NA 7. Evaporation Rate: NA 1 mg/M³ 8. Auto Ignition Rate: NA 1 mg/M³ 9. Appearance & Odor: gray-black & odorless 10. Physical State: solid pH: NA 5.0 mg/M³ 15.0 mg/M³
	Molybdenum Cobalt	7439-98-7	0-5 0-1.0		5.0 mg/M ³ 15.0 mg/M ³ 0.1 mg/M ³	
V. Emergency Medical Procedures I. First Aid: In case of excessive exposure, remove to fresh air, administer oxygen, and seek physicians assistance.				V. Personal Protection Information Respiratory: When engineering or administrative controls cannot maintain exposures below permissible limits during welding, brazing, machining, and other processes which may generate airborne contaminants, use appropriate NiOSH/MSHA approved respirator. Gloves: Suitable for protection against physical injury		
				Eye: Safety glasses or gogles when there		ring particles

Date Revised: January 11, 2002

Greenville Tube

Material Safety Data Sheet

VI. HEALTH HAZARD DATA:	Material Safety Data Sheet					
huming would be designed to the natural state of	o not present an inhalation, ingestion, or contact hazard. However, operation such as					
parting, wolding, sawing, brazing, and gir	nding may result in the following effects if exposures exceed permissible limits as listed in Section II.					
(a) Major Exposure Hazard	The second in cost of the					
X Inhalation	Skin Contact Skin Absorption Eye Contact Ingestion					
	Eye Contact Ingestion					
Effects of Overexposure						
ACUTE:	Exposure to high concentrations of metallic fumes or dusts may result in irritation					
	and/or sensitization of the respiratory tract, lungs, mucous membranes, and eyes					
1	Excessive inhalation of fumos from many materials, mucous membranes, and eyes					
1	Excessive inhalation of furnes from many metals can produce an acute reaction known as "metal furne fever" Dermititis					
1						
CHRONIC:	Siderosis, Bronchitis, pneumonitis, inflammation and/or ulceration of upper respiratory tract,					
	Kidney or liver damage					
İ	Various forms of dermititis,					
	Based on available information, there does not appear to be any evidence that exposure to welding fume induces human cancer. Inflamation of the joints					
1	internation of the joints					
Signs and Symtoms of Redness, swelling, itching of skin and eyes. Coughing, wheezing, shortness of breath, decreased pulmonary function.						
Exposure	Metal fume fever: chills and fever, a metallic taste in the mouth, dryness and irritation of the throat.					
	sleepiness, lower back pain, and edema, loss of appetite, jaundice.					
VII. FIRE AND EXPLOSION HAZARD	DATA: REACTIVITY DATA: SPECIAL PRECAUTIONS:					
1. Flash Point: NA						
2. LEL: NA	11 Wolding & Calting-adoquate Vertillation and/or approved					
3. UEL: NA	Incompatibility: None respiratory protection should be provided if permissible Products of Decomposition: exposure limits are exceeded.					
4. Extinguishing Media: NA	Products of Decomposition: exposure limits are exceeded. 1. Metal Fume: Iron Oxide					
5. Special Fire Fighting Precautions: N						
o. oposici i io i igrang i roccations.	3. Chromium, Molybdenum					
	5. Ontomium, Morybuenum					