Kim Kuda B180706

MATERIAL SAFETY DATA SHEET



Re -issue Date: October, 5 2015

9900 Emmett F Lowry Expy Texas City, TX 77591

1.800.231.9450 Texas City: 409.765.9003 Houston: 281.480.7764 Fax: 409,765.7115 www.farmerscopper.com

SECTION I. MATERIAL IDENTIFICATION Copper/Copper Alloys

See attached alloy composition sheets for alloy presence and percentages of alloying ingradients.

SECTION II. HAZARDOUS INGREDIENTS Copper/Copper Alloys

	CAS Number		OSHA-PEL 8-hr TWA	ACGRI-TLV 8-HR TWA (1988-89)	ACGIH STEL (1988-89)
Aluminum #	(7429-90-5)	(Dust)	15 mg/m³	10 mg/m²	- 1
		(Fume)	5 mg/m³	5 mg/m³	-
Antimony #	(7440-36-0)		0.5 mg/m³	0.5 mg/m³	**
Arsenic #	(7440-38-2)		0.5 mg/m²	0.02 mg/m²	
Beryllium #	(7440-41-7)		0,002 mg/m³	0.002 mg/m³	0.005*
Blamyth telluride	(1304-82-1)	(Dust)	15 mg/m²	15 mg/m³	••
Boron oxide	(1303-86-2)	(Dust)	15 mg/m³	10 mg/m³	-
Cadmlum #	(7440-43-9)	(Dust)	0.2 mg/m³	0.05 mg/m³	
	, ,	(Fume)	0.1 mg/m³	0.05 mg/m³°	••
Czickum oxide	(1305-78-8)		5 mg/m³	5 mg/m³	
Carbonblack	(1333-86-4)		3.5 mg/m ³	••	. ••
Chromium #	(7440-47-3)		1 mg/m³	0.5 mg/m³	₩
Cobalt #	(7440-48-4)		0,05 mg/m²	. 0.1 mg/m ^a	
Copper#	(7440-50-8)	(Dust)	1 mg/m ^s	1 mg/m³	
	• •	(Fume)	0.1 mg/m ¹	0.2 mg/m³	•
Iron	(1309-37-1)	, ,	10 mg/m²	5 mg/m³	
	•		_	(As iron axide fume)	-
Load # @	(7438-92-1)		0.05 mg/m³	0.15 mg/m³	**
Lithium hydride	(7580-67-8)		0.025 mg/m³	.025 mg/m³	· •
Manganese #	(7439-96-5)	(Dust)	5 mg/m²*	5 mg/m³*	**
	•	(Fume)	**	1 mg/m²	3 mg/m³
Magnesium oxide	(1309-48-4)	(Dust)	15 mg/m³	10 mg/m³	-
Nickel #	(7440-02-0)	: "	1 mg/m²	1 mg/m³	••
Phosphorus #	(7723-14-0)		0.1mg/m³	0.1 mg/m³	
Selenium	(7782-49-2)		0.2 mg/m³	0.2 mg/m³	, -
Silicon	(7440-21-3)	(Dust)	10 mg/m³	10 mg/m O	-
	•	(Fume)	5 mg/m³	-	
Silver #	(7440-22-4)		0.01 mg/m³	0.1 mg/m²	**
Sujphur Dioxide #	(7446-09-5)		5 mg/m³	5 mg/m³	5/10 mg/m³
Tellurium #	(13494-60-9)		0.1 mg/m³	0.1 mg/m³	
Tin Ø	(7440-31-5)		2 mg/m³	2 mg/m³	0.2 mg/m ¹
					(contemplated)
- Titanium dioxide	(13483-87-7)	(Dust)	15 mg/m"	10 mg/m³	-
Zinc #	(1314-13-2)	(Dust) Φ	10 mg/m²	10 mg/m³	***************************************
		(Fume)	5 mg/m²	5 mg/m²	10 mg/m³ 10 mg/m³
Zirconium	(7440-67-7)		5 mg/m³	5 mg/m*	i v mym:

Zirconium (**Celling Limit **)

**Celling Limit **

**Celling Limit **

**Nois: antimony trioxide, beryillium, cadmium, chromium, cobalt-chromium alloy, lead and nickel have been identified as potential human carcinogens. If denotes a toxic chemical or chemicals subject to reporting requirements of Section 313 of Tale III of the S.A.R.A. of 1986 and CFR Part 372.

**O Value is for total dust containing no asbestos and less than 1% free silicon.

**O Contemplated change to 0.2 STEL and 0.1 TWA.

O Under court remand.



SECTION III. PHYSICAL DATA

Physical Form: Boiling Point;

Vapor Pressure:

Evaporation Rate:

Solid

Not Applicable

Freeze-Mak Temperature:

Approximately 1290" - 2260"F

Not Applicable
Not Applicable

Specific Gravity: Vapor Density Solubility in H₂O: 7.45 -- 9.00 Not Applicable Insoluble

Color: ... Odor: Silver or Yellow to Red

None

SECTION IV. FIRE AND EXPLOSION DATA

Flash Point: (Method Used) Not Applicable

Flammable Limits (LEL-UEL) Not Applicable

Extinguishing Media: See Below
Auto Ignition Temp.-Not Applicable

Special Fire Fighting Procedures: Solid massive form is not combustible. Fire and explosion hazards are moderate when material is in the form of dust and exposed to heat, flames, chemical reaction, or in contact with powerful oxidizers. Use special mixtures of dry chemical or sand, Firefighters should wear NIOSH/MSHA self-contained breathing apparatus and protective clothing. Motion metal may react violently with water.

SECTION V. REACTIVITY DATA

Stability: Stable

Conditions to Avoid: Stable under normal conditions of transport and storage. Molten metal may react violently with water.

incompatibility (Materials to Avoid): Acids, bases, and oxidizers.

Hazardous Decomposition or Byproducts: Metal fume.

Hazardous Polymerization: Will not occur.

SECTION VI. HEALTH HAZARD DATA

Permissible exposure limits and threshold limit values. See Section II,

Routets) of Entry: Inhalation: Yes; Skin: Yes; ingestion: Yes

Under normal handling conditions the solid alloy presents no significant health hazards. Processing of the alloy by dust or fume producing operation (grinding, buffing, healing, weiding, etc.) may result in the potential for exposure to sirborne metal particulates or fume. The exposure levels in Section II are relevant to fumes and dusts.

Effects of Overexposure:

Aliminum—Excessive exposure to aluminum tume and dust has been associated with tung disease, but this effect is probably due to simultaneous silics exposure.

Aritimeny—Antimony and its compounds are irritating to the skin and mucous membranes and are systemic poisons. Effects are reported to include metallic tasts in the mouth, vomiting, colle, loss of appetite and weight, cardiac problems, and diarrhea, in addition, dermatitis may result which starts as an inflammation of the hair follicles and can progress through pus formation and sloughing to leave a contracted scar.

Beryflium—inhalation of beryflium dust or fume may result in the production of an acute or chronic systemic disease depending upon the level of exposure and the beryflium compound involved. Granulomatous lesions of the skin, liver, kidneys, spleen, and lymph nodes have been reported.

Damage to the lungs may be in both the acute and chronic forms, both of which have similar signs and symptoms. These include a relatively non-productive cough, progressive difficulty in breathing, loss of appetite, and loss of weight. The major difference between the two is the suddenness of onset and the rate of progression, in the acute form, the symptoms appear in several hours to several weeks after exposure and there is usually rapid progression of signs including dyspnes, ancrexia, and extreme weight loss. Complete recovery is possible and fatal cases usually rest from acute heart disease, in chronic beryllium disease, the symptoms or signs are generally delayed in their onset and are persistent in nature. They may be triggered or aggravated by stresses such as pregnancy, respiratory infection, and thyrotoxicosis, in the progression of the disease, symptoms of heart disease may occur.

Beiyilium is also a suspected human carcinogen and has caused cancer in laboratory animals.

Cadmium—inhalation of cadmium furnes may cause respiratory irritation with a sore, dry throat and a metallic tasie followed by a cough, chest pain, and difficulty in breathing. Bronchitis, pneumonitis, and pulmonary edema have been reported as a result of the initiation of the furnes. Headaches, dizziness, loss of appetite, and weight loss have also been reported and the liver, kidneys and bone marrow may be injured by the presence of the metal.

Continued exposure to lower levels of cadmium has resulted in chronic poisoning characterized by irreversible lung damage and kidney damage. A single, high level exposure to cadmium can cause severe lung irritation which may be fatal. Cadmium is also a suspected human carcinogen.

Chromium—in some workers, chromium compounds act as allergens and may cause dermatitis and may also produce pulmonary sensitization. Chromic acid and chromates have a direct corrosive effect on the skin and the mucous membranes of the upper respiratory tract. Although rare, there may be the possibility of skin and pulmonary sensitization. IARC has determined that there is sufficient evidence of increased lung cancer among workers in the chromate-producing industry and possible chromium alloy workers. This determination is supported by sufficient evidence for carcinogenicity to animals and possible mutagenicity teating of Cr VI compounds.

Cobalt—Cobalt has been reported as causing hypersensitization type dermatitis in individuals who are susceptible. Animal studies have shown that particulate cobalt is an acutely irritating substance and industrial exposures, possibly combined with small amounts of silica, are reported capable of producing serious pneumoconics which is initially of an insidious nature.

Copper—Melting, grinding, cutting of copper may produce furnes or dust exposure and breathing these furnes or dust may present potentially significant health hazards. Furnes of copper may cause metal furne fever with flu-like symptoms and skin and hair discoloration. While industrial dermatitis has not been reported, keratinization of the hands and the soles of the feet has been reported. Systemically as well, copper dust and furne cause irritation of the upper respiratory tract, metallic taste in the mouth, and natures.

iten.—The inhalation of Iron oxide fumes or dust may cause an apparent benign pneumoconicals which is called siderosis. This disease is reported to be disabiling, but makes x-ray diagnosis of other lung conditions difficult or impossible.

Lead—Short term exposure: Lead is an accumulative poison, inhalation effects of exposure to fumes or dust of inorganic lead may not develop quickly. Symptoms may include decreased physical fitness, fatigue, sisep disturbance, headache, aching bones and muscles, constipation, abdominal pains, and decreasing appetite. The effects are reversible and complete recovery is possible, inhalation of large amounts of lead may lead to selzures, coms, and death.

Lead...Long term exposure: Long term exposure can result in a buildup of lead in the body and more severe symptoms. These include anemis, pale skin, a blue line at the gum margin, decreased handgrip strength, abdominal pain, severe constitution, nauses, vomiting, and paralysis of the wrist joint. Prolonged exposure may also result in kidney damage. If the nervous system is affected, usually due to very high exposures, the resulting effects include severe headache, convulsions, come, delirium, and death. Alcohol ingestion and physical exertion may bring on symptoms. Continued exposure can result in decreased fertility and/or increased chances of miscarriage or birth defects.

Manganese—Chronic manganese poisoning may result from inhalation of dust or fume. The central nervous system is the chief site of the injury, and there also may be adverse blood and kidney effects. Chronic manganese poisoning is not a fatal disease although it is extremely disabiling. Some individuals may be hypersusceptible to manganese. Freahly formed manganese tume has caused fever and chilis similar to metal tume fever.

Nickel—The most common aliment arising from contact with nickel or its compounds is an allergic dermatitis known as "nickel lich" which usually occurs when the skin is moist. Generally nickel and most salts of nickel do not cause systemic poisoning, but nickel has been identified as a suspected cardinogen. There can also be adverse effects to the lungs and nasal cavilles.

Silicon—Accumulation in lungs may be responsible for benign pneumoconiosis, but is not considered to be responsible for pulmonary functional impairment or respiratory symptoms.

Tin-The inhalation of inorganic tin furnes or dust may cause an apparent benign pneumoconics is called stannosis which is reported not to be disabiling.

Zinc (as Oxide)—Zinc is very low in toxicity but inhalation of fumes may cause "metal fume fever." Onset of symptoms may be delayed 4–12 hours and include irritation of the nose, mouth and throat, cough, atomach pain, headache, nausea, vomiting, metallic taste, chills, fever, pains in the muscles and joints, thirst, bronchitis or pneumonia and a bluish tint to the skin. These symptoms go away in 24–48 hours and leave no effect.

NOTE: Antimony trioxide, beryllium, cadmium, chromium, cobait-chromium alloy, lead and nickel have been identified as potential human carcinogens.

EMERGENCY FIRST AID PROCEDURES:

Eye Contact Flush well with running water to remove particulate. Get medical attention.

Skin Contact Vacuum off excess dust, Wash well with sosp and water,

Inhalation Remove to fresh air, Get medical attention,

Ingestion Seek medical attention if large quantities of material have been ingested,

SECTION VII. PRECAUTIONS FOR SAFE HANDLING OR USE

Steps to be Taken in Case Material is Released or Spitled: No special precautions are necessary for spitls of bulk material. If large quantities of dust are spitled, remove by vacuuming or wet sweeping to prevent heavy concentration of airborne dust, if large quantities or bases) containing solubilized metal are spitled evacuate unprotected personnel from area. Absorb tiquid by means of varmiculite, dry sand or similar material, Follow federal, state, and local regulations concerning the disposal of waste.

Waste Disposal Method: Dispose of in accordance with federal, state, and local regulations. Cleanup personnel should wear

respirators and protective clothing. Ventilate area of refease.

Precautions to be Taken in Handling and Storing: Store material away from incompatible materials and keep dust from sources of ignition.

Other Precautions: See all other sections of this MSDS.

SECTION VIII. CONTROL MEASURES

Respiratory Protection: If exposure above the PEL or TLV, NIOSH/MSH approved respirator for fume or dust, dependent upon the source of airborne contaminant.

Ventilation: Required if dust or lume created in handling or working on this material.

Local Exhaust: Required if dust or fume created in handling or working on this material and threshold limits are being approached.

Mechanical (general): As above to reduce zirbome dust or lume levels.

Protective Gloves: Required for melt, grind, cut or weld operations. Select glove approved for the specific operation.

Eye Protection: Required for melt, grind, cut; or weld operations. Minimum requirement of safety glasses with side shields for these operations. Malting and welding may require special eye protection including face shields and specially tinted glass. Grinding operations may also require face shields.

Other Protective Clothing or Equipment: As required for the work done on or with the metal.

Work/Hyglene Practices: As required for the work done with lead bearing materials. Meet requirements of the OSHA lead standard where necessary. Always evaluate the jobs done on this product in accordance with OSHA or relevant state, federal, or local standards.

IMPORTANT

LIABILITY DISCLAIMER

The information contained in this Material Safety Data Sheet (MSDS) is believed to be correct as it was obtained from sources we believe are reliable, including: "Threshold Limit Values & Biological Exposure Indices for 1988–89" (American Conference of Government & Industrial Hygienists), Air Contaminates—Permissible Exposure Limits (Title 29, Code of Federal Regulations, part 1910.1000—OSHA), and OSHA (Cleveland Area Office) letter of 6/15/89. However, no representations, guarantees or warranties of any kind are made as to its accuracy, suitability for particular applications, hazards connected with the use of the material, or the results to be obtained from the use thereof. User assumes all risks and liability of any use, processing or handling of any material, variations in methods, conditions and equipment used to store, handle or process the material and hazards connected with the use of the material are solely the responsibility of the user and remain at his sole discretion.

Compliance with all applicable federal, state, and local laws and regulations remains the responsibility of the user, and the user has the responsibility to provide a safe work place, to examine all aspects of its operation and to determine if or where precautions, in addition to those described herain, are required.

Note: The copper and copper alloy products are in solid form and will not result in an environmental exposure in such form. We cannot anticipate all the processes or applications to which this product might be subjected or which might create exposures. The information supplied has been furnished by our suppliers and consequently, our company assumes no responsibility for the accuracy or completeness of the data contained herein.