AOS 4 V5 机架组装示意图

Frame Assembly Guide

1. 顶板 Top plate	x1
2. 底板 Bottom plate	x1
3. 机臂	x4
4. 中板 Counter plate	x1
5. 支撑板 Supporting plate	x1
6. O3 摄像头固定侧板 O3 camera side plate	x2
7. CNC 摄像头侧板 CNC camera side plate	x2
8. 脚垫打印件 Arm guard TPU	x4
9. 图传天线座打印件 Antenna TPU	x1
10. 接收机座打印件 Receiver mount TPU	x1
11. 固定XT60上盖打印件 XT60 upper mount TPU	x1
12. 固定XT60下盖打印件 XT60 bottom mount TPU	x1
13. 摄像头硅胶侧板 Silicone camera side plate	x2
14. M3*20 圆形网纹铝柱 M3*20 Al. standoffv	x7
15. M2*23 圆形网纹铝柱 M2*23 Al. standoffv	x2
16. M3*6 沉头内六角螺丝 M3*6 countersunk hex screw	x7
17. M2*8 内六角螺丝 M2*8 hex screw	x14
18. M2*6 内六角螺丝 M2*6 hex screw	x8
19. M3*10 沉头内六角螺丝 M3*10 countersunk hex screw	хЗ
20. M3*12 沉头内六角螺丝 M3*12 countersunk hex screw	x5
21. M1.6*10 杯头内六角螺丝 M1.6*10 socket head cap	x5
22. M3*6 内六角螺丝 M3*6 hex screw	x3
23. M3*20 内六角螺丝 M3*20 hex screw	x5

24. M2*10 内六角螺丝 M2*10 hex screw	x3
25. M2*14 内六角螺丝 M2*14 hex screw	x3
26. M2 防松自紧螺母 M2 lock nut	x3
27. M2*5 内六角螺丝 M2*5 hex screw	x5
28. M2*3 沉头内六角螺丝 M2*3 countersunk hex screw	x5

	(附赠)/(Additional parts)	
	模拟摄像头固定侧板 Analog camera side plate	x2
2.	M2*5 沉头内六角螺丝 M2*5 countersunk hex screw	x5 ¦
3.	M3 防松自紧螺母 M3 lock nut	x5 ¦
4.	电源线+插头 Power cable + plug	x1
5.	集线管 Motor wire protecto	x4 !
6.	15*250 超纤皮电池扎带 15*250 Battery strap	x1
7.	20*250 超纤皮电池扎带 20*250 Battery strap	x1
8.	电池硅胶防滑垫 Battery pad	x2
9.	自锁尼龙扎带 Self-locking nylon zip ties	x4 !
10.	M3 螺母 M3 nut	x5
11.	M1.6*7 内六角带垫螺丝 M1.6*7 hex washer head screw	x5
12.	通用贴纸 Sticker	x1

