AOS 5 V5

机架组装示意图 Frame Assembly Guide

1.	顶板 Top plate	x1	26. M2 防松自紧螺母 M2 lock nut	хЗ
	底板 Bottom plate	x1	27. M3 防松自紧螺母 M3 lock nut	x5
	机臂 Arm	x4	28. M2*3 沉头内六角螺丝 M2*3 countersunk hex screw	x5
4.	中板 Counter plate	x1	29. M2*6 内六角螺丝 M2*6 hex screw	x13
5.	O3 摄像头固定侧板 O3 camera side plate	x2	30. M2 螺母 M2 nut	хЗ
6.	CNC 摄像头侧板 CNC camera side plate	x2	31. O4 Pro 支架 TPU O4 Pro bracket TPU	x2
7.	脚垫打印件 Arm guard TPU	x4	32. O4减震垫 TPU O4 Vibration DampersTPU	x2
	双孔图传天线座打印件 Dual Antenna VTX TPU Mount	x1	,,,,,(附赠)/(Additional parts)	
	可调节狗座底座打印件 GoPro bottom stand TPU	x1	1. 模拟摄像头固定侧板 Analog camera side plate	x2
	接收机座注塑件 Receiver mount	x1	2. M2*5 沉头内六角螺丝 M2*5 countersunk hex screw	x5
11.	固定XT60上盖打印件 XT60 upper mount TPU	x1	3. 内六角扳手 3. Allen wrench	x1
	固定XT60下盖打印件 XT60 bottom mount TPU	x1	4. M5法兰螺母 4. M5 nut	x1
	摄像头硅胶侧板 Silicone camera side plate	x2	5. M5*20 内六角螺丝 M5*20 hex screw	x1
	M2*23 圆形网纹铝柱 M2*23 Al. standoff	x2	集线管 6. Motor wire protecto	x4
15.	M3*20 圆形网纹铝柱 M3*20 Al. standoffv	x7	7. 15*250 超纤皮电池扎带 7. 15*250 Battery strap	x1
16.	M3*8 沉头内六角螺丝 M3*8 countersunk hex screw	x7	20*250 超纤皮电池扎带 8.20*250 Battery strap	x1
17.	M3*12 沉头内六角螺丝 M3*12 countersunk hex screw	x3	9. 电池硅胶防滑垫 Battery pad	x2
18.	M3*16 沉头内六角螺丝 M3*16 countersunk hex screw	x5	自锁尼龙扎带 10. Self-locking nylon zip ties	х6
19.	M3*6 内六角螺丝 M3*6 hex screw	x10	11. 强用贴纸 Sticker	x1
20.	M3*8 内六角带垫螺丝 M3*8 hex washer head screw	x3	12. M2*5 内六角螺丝 12. M2*5 hex screw	x5
	M3*20 内六角螺丝 M3*20 hex screw	x5	13. Power cable + plug	x1
	M3*10 内六角螺丝 M3*10 hex screw	x14	14. O4 Pro支架(ND镜) TPU 14. O4 Pro bracket (ND filter)TPU	x2
25.	M1.6*10 杯头内六角螺丝 M1.6*10 socket head cap	x5	15. O4 支架 TPU 15. O4 bracket TPU	x2
24.	M2*10 内六角螺丝 M2*10 hex screw	x3	图传天线座打印件 16. Antenna TPU	x1
25.	M2*14 内六角螺丝 M2*14 hex screw	x3	17. M2*6 countersunk hex screw	x5
			\	

