AOS 4 V5

机架组装示意图 Frame Assembly Guide

1. 顶板 Top plate	x1
2. 底板 Bottom plate	X1
3. Arm	X
4. 中板 Counter plate	x1
5. 支撑板 Supporting plate	x1
6. O3 摄像头固定侧板 6. O3 camera side plate	×2
7. CNC 摄像头侧板 CNC camera side plate	X
8. 脚垫打印件 Arm guard TPU	X
9. 双孔图传天线座打印件 Dual Antenna VTX TPU Mount	x1
10. 接收机座注塑件 Receiver mount	x1
11. 固定XT60上盖打印件 XT60 upper mount TPU	X1
12. 固定XT60下盖打印件 XT60 bottom mount TPU	x1
13. 摄像头硅胶侧板 Silicone camera side plate	X
14. M3*20 圆形网纹铝柱 M3*20 Al. standoffv	X
15. M2*23 圆形网纹铝柱 M2*23 Al. standoffv	X
16. M3*6 沉头内六角螺丝 M3*6 countersunk hex screw	X.
17. M2*8 内六角螺丝 M2*8 hex screw	x1
18. M2*6 内六角螺丝 M2*6 hex screw	x1
19. M3*10 沉头内六角螺丝 M3*10 country M hex screw	x
20. M3*12 沉头内六角螺丝 M3*12 countersunk hex screw	X
21. M1.6*10 杯头内六角螺丝 M1.6*10 socket head cap	X!
22. M3*6 内六角螺丝 M3*6 hex screw	X
23. M3*20 内六角螺丝 M3*20 hex screw	X!
24. M2*10 内六角螺丝 M2*10 hex screw	X
25. M2*14 内六角螺丝 M2*14 hex screw	X

26. M2 防松自紧螺母 M2 lock nut	x3
27. M2*5 内六角螺丝 M2*5 hex screw	x5
28. M2*3 沉头内六角螺丝 M2*3 countersunk hex screw	x5
29. M2 螺母 M2 nut	x3
30. O4 Pro 支架 TPU O4 Pro bracket TPU	x2
31. O4减震垫 TPU O4 Vibration DampersTPU	x2

	(附赠)/(Additional parts)	,
١.	模拟摄像头固定侧板 Analog camera side plate	x2
2.	M2*5 沉头内六角螺丝 M2*5 countersunk hex screw	x5 !
3.	M3 防松自紧螺母 M3 lock nut	x5 ¦
4.	电源线+插头 Power cable + plug	x1 ¦
5.	集线管 Motor wire protecto	x4 ¦
6.	15*250 超纤皮电池扎带 15*250 Battery strap	x1
7.	20*250 超纤皮电池扎带 20*250 Battery strap	x1
	电池硅胶防滑垫 Battery pad	x2
	自锁尼龙扎带 Self-locking nylon zip ties	x4
10.	M3 螺母 M3 nut	x5 !
11.	通用贴纸 Sticker	x1
12.	M1.6*7 带垫内六角螺丝 M1.6*7 hex screw head screw	x5 ¦
13.	M2*6 沉头内六角螺丝 M2*6 countersunk hex screw	x5
	O4 Pro支架(ND镜) TPU O4 Pro bracket (ND filter)TPU	x2
	O4 支架 TPU O4 bracket TPU	x2
16.	图传天线座打印件 Antenna TPU	x1



