

CINEFLOW 5 碳板机架组装说明书

CINEFLOW 5 Frame Assembly Guide



组装说明: Part One




包装里有:


Packing list

0	顶板 Top plate	X1	2	M3*9mm半圆头螺丝 M3*9mm half round head screws	X14
2	中板 Upper plate	X1	23	M3*8mm半圆头螺丝 ^{M3*8mm} half round head screws	Х3
8	夹板 Mid-lower plate	X1	24	M3*6mm半圆头螺丝 ^{M3*6mm} half round head screws	X12
4	底板 Bottom plate	X1	3	M2.5*6mm半圆头螺丝 M2.5*6mm half round head screws	Х3
6	机臂A ArmA	X2	26	M2*5mm半圆头螺丝 ^{M2*5mm half round head screws}	X10
6	机臂B ArmB	X2	4	M2*4mm半圆头螺丝 M2*4mm half round head screws	Х3
7	铝合金侧板 CNC camera side plate	X2	28	M2*5mm半圆头自攻螺丝 ^{M2*5mm pan head self-tapping screw}	Х3
8	侧板+发光板(已安装好) Side panels + LED board (Pre-install LED)	X2	29	XT60EW-M 公头 XT60EW-M battery plug	X1
9	图传天线座 Antenna mount	X1	30	格纹硅胶电池防滑垫 Battery pad	X2
10	接收机座TPU打印件 Receiver mount TPU	X1	3	集线管 Motor wire shield tube	X4
•	狗座底座 GoPro bottom stand	X1	32	底座LED灯 Base mount LED	X1
Ø	脚垫 Arm guard	X4	(昨	赠)/(Additional parts)	
B	前保护杠 Front bumpers	X2	3	LED 导光条 LED light strap	X4
1	LED灯显LOGO打印件 LED logo TPU	X1	34	20*250mm超纤皮电池扎带 ^{20*250mm Battery strap}	X2
Œ	硅胶侧板 Silicone camera side plate	X2	3	套机通用贴纸V4 Sticker V4	X1
16	M3*30圆形网纹铝柱 M3*30mm standoff	Х3	36	内六角扳手 A ll en wrench	X1
D	M3*22圆形网纹铝柱 M3*22mm standoff	Х3	3	M5防松螺母 M5 screw nut	X1
13	M3 防松自紧螺母 M3 screw nut	X5	38	M5*20mm平头螺丝 ^{M5*20} hex screw	X1
4	M3*28mm半圆头螺丝	X5	39	转接线 IPEX to RP-SMA F Adapter Cable 16CM	X2
19	M3*28mm half round head screws			IT EX TO ICE SIMA E Adapter Cable Tocini	
20	M3*28mm half round head screws M3*14mm半圆头螺丝 M3*14mm half round head screws	X5	40	3P双头端子线 3 pin terminal connector	X1
_	M3*14mm半圆头螺丝	X5 X7	_	3P双头端子线	X1 X2


2 ^{组装说明}:



3 组装说明: Part Three



4 组装说明: Part Four



5 组装说明: Part Five

