

CINELR 7 碳板机架组装说明书

CINELR 7 Frame Assembly Guide



1 组装说明 Part One




包装里有:


Packing list

0	顶板 Top plate	X1	2	M3*10mm半圆头螺丝 M3*10mm half round head screws	X14
2	中板 Upper plate	X1	23	M3*8mm半圆头螺丝 M3*8mm half round head screws	X14
8	夹板 Mid-lower plate	X1	24	M2.5*6mm半圆头螺丝 M2.5*6mm half round head screws	Х3
4	底板 Bottom plate	X1	25	M2*5mm半圆头螺丝 M2*5mm half round head screws	X10
6	机臂A ArmA	X2	26	M2*4mm半圆头螺丝 M2*4mm half round head screws	Х3
6	机臂B ArmB	X2	4	M2*5mm半圆头自攻螺丝 M2*5mm pan head sel f -tapping screw	Х3
7	铝合金侧板 CNC camera side plate	X2	28	XT60EW-M 公头 XT60EW-M battery plug	X1
8	侧板+发光板 (已安装好) Side panels + LED board (Pre-install LED)	X2	29	格纹硅胶电池防滑垫 Battery pad	X2
9	图传天线座 Antenna mount	X1	30	10*10mm集线管 10*10mm Motor wire shie l d tube	X4
10	接收机座TPU打印件 Receiver mount TPU	X1	3	50*10mm集线管 50*10mm Motor wire shie l d tube	X4
1	狗座底座 GoPro bottom stand	X1	32	底座LED灯 Base mount LED	X1
12	脚垫 Arm guard	X4	(附	赠)/(Additional parts)	
B	前保护杠 Front bumpers	X2	③	LED导光条 LED light strap	X4
14	LED灯显LOGO打印件 LED logo TPU	X1	34	20*300mm超纤皮电池扎带 ^{20*300mm} Battery strap	X2
Ð	硅胶侧板 Silicone camera side plate	X2	35	套机通用贴纸V4 Sticker V4	X1
16	M3*30圆形网纹铝柱 M3*30mm standoff	Х3	36	内六角扳手 A ll en wrench	X1
Ð	M3*21圆形网纹铝柱 M3*21mm standoff	Х3	3	M5防松螺母 M5 screw nut	X1
13	M3 防松自紧螺母 M3 screw nut	X5	38	M5*20mm平头螺丝 M5*20 hex screw	X1
1	M3*30mm半圆头螺丝 M3*30mm half round head screws	X5	39	转接线 IPEX to RP-SMA F Adapter Cable 22CM	X2
20	M3*16mm半圆头螺丝 ^{M3*16mm} ha lf round head screws	X5	40	3P双头端子线 3 pin terminal connector	X1
4	M3*12mm半圆头螺丝 M3*12mm half round head screws	X7	4	硅胶线 Power cable	X4


2 组装说明: Part Two



3 ^{组装说明}:



4 ^{组装说明}:



5 组装说明: Part Five

