

CINELR 7 碳板机架组装说明书

CINELR 7 Frame Assembly Guide




■ 组装记明 ■ Part One




包装里有 / Packing list:

0	顶板 Top plate	X1	24	M2.5*6mm半圆头螺丝 M2.5*6mm half round head screws	X3
2	中板 Upper plate	X1	25	M2*5mm半圆头螺丝 M2*5mm half round head screws	X10
3	夹板 Mid-lower plate	X1	26	M2*4mm半圆头螺丝 M2*4mm half round head screws	Х3
4	底板 Bottom plate	X1	2	M2*5mm半圆头自攻螺丝 M2*5mm pan head self-tapping screw	Х3
6	机臂A ArmA	X2	28	XT60EW-M 公头 XT60EW-M battery plug	X1
6	机臂B ArmB	X2	29	格纹硅胶电池防滑垫 Battery pad	X2
7	铝合金侧板 CNC camera side plate	X2	<u>30</u>	10*10mm集线管 10*10mm Motor wire shie l d tube	X4
8	侧板+发光板(已安装好) Side panels + LED board (Pre-install LED)	X2	3	50*10mm集线管 50*10mm Motor wire shield tube	X4
9	图传天线座 Antenna mount	X1	32	底座LED灯 Base mount LED	X1
O	接收机座TPU打印件 Receiver mount TPU	X1	(附	赠)/(Additional parts	;)
0	狗座底座 GoPro bottom stand	X1	3	LED导光条 LED Light Tube	X4
Ø	脚垫 Arm guard	X4	34	20*300mm超纤皮电池扎带 ^{20*300mm Battery strap}	X2
B	前保护杠 Front bumpers	X2	3	套机通用贴纸V4 Sticker V4	X1
1	LED灯显LOGO打印件 LED logo TPU	X1	3 6	内六角扳手 Allen wrench	X1
B	硅胶侧板 Silicone camera side plate	X2	3	M5防松螺母 M5 screw nut	X1
16	M3*30圆形网纹铝柱 M3*30mm standoff	X3	3 B	M5*20mm平头螺丝 M5*20 hex screw	X1
Ð	M3*21圆形网纹铝柱 M3*21mm standoff	X3	39	转接线 IPEX to RP-SMA F Adapter Cable 22CM	X2
ß	M3 防松自紧螺母 M3 screw nut	X5	40	3P双头端子线 3 pin terminal connector	X1
Ø	M3*30mm半圆头螺丝 M3*30mm half round head screws	X5	4	硅胶线 Power cable	X4
20	M3*16mm半圆头螺丝 M3*16mm half round head screws	X5	4 2	LED灯带 LED strip	X3
a	M3*12mm半圆头螺丝 M3*12mm half round head screws	X7	4 3	灯带控制板 LED control module	X1
22	M3*10mm半圆头螺丝 M3*10mm half round head screws	X14	4	透明热缩管 Transparent clear heat shrink tubing	X1
23	M3*8mm半圆头螺丝 M3*8mm half round head screws	X14	4 5	双面胶 Double sided tape	X1


2 ^{组装说明:} Part Two



4 组装说明: Part Four



3 ^{组装说明:} Part Three



组装说明: Part Five

