AOS 5 V5

机架组装示意图 Frame Assembly Guide

1. ^{顶板} Top plate	x1	26. M2 防松自紧螺母 M2 lock nut
2. 底板 Bottom plate	x1	27. M3 防松自紧螺母 M3 lock nut
3. 机臂	x4	28. M2*3 沉头内六角 ⁹ M2*3 countersunk
4. 中板 Counter plate	x1	29. M2*6 内六角螺丝 M2*6 hex screw
5. O3 摄像头固定侧板 O3 camera side plate	x2	,, (附赠)/(Add
6. CNC 摄像头侧板 CNC camera side plate	x2	1. 模拟摄像头固定侧标 Analog camera side
7. 脚垫打印件 Arm guard TPU	x4	2. M2*5 沉头内六角螺
8. 图传天线座打印件 Antenna TPU	x1	3. 内六角扳手 Allen wrench
9. 可调节狗座底座打印件 GoPro bottom stand TPU	x1	4.M5法兰螺母 M5 nut
10. 接收机座打印件 Receiver mount TPU	x1	5. M5*20 内六角螺丝 M5*20 hex screw
11. 固定XT60上盖打印件 XT60 upper mount TPU	x1	集线管 6. Motor wire protect
12. 固定XT60下盖打印件 XT60 bottom mount TPU	x1	7. 15*250 超纤皮电池 7. 15*250 Battery str
13. 摄像头硅胶侧板 Silicone camera side plate	x2	8. 20*250 超纤皮电池 8. 20*250 Battery str
14. M2*23 圆形网纹铝柱 M2*23 Al. standoff	x2	9. 电池硅胶防滑垫 Battery pad
15. M3*20 圆形网纹铝柱 M3*20 Al. standoffv	x7	¦ 10. 自锁尼龙扎带 Self-locking nylon z
16. M3*8 沉头内六角螺丝 M3*8 countersunk hex screw	x7	11. 通用贴纸 11. Sticker
17. M3*12 沉头内六角螺丝 M3*12 countersunk hex screw	x3	12. M2*5 内六角螺丝 12. M2*5 hex screw
18. M3*16 沉头内六角螺丝 M3*16 countersunk hex screw	x5	L 13. 电源线+插头 Power cable + plug
19. M3*6 内六角螺丝 M3*6 hex screw	x10	
20. M3*8 内六角带垫螺丝 M3*8 hex washer head screw	x3	
21. M3*20 内六角螺丝 M3*20 hex screw	x5	
22. M3*10 内六角螺丝 M3*10 hex screw	x14	
23. M1.6*10 杯头内六角螺丝 M1.6*10 socket head cap	x5	
24. M2*10 内六角螺丝 M2*10 hex screw	x3	
25. M2*14 内六角螺丝 M2*14 hex screw	x3	

ΧI	26. M2 lock nut	ХЭ	
x1	27. M3 防松自紧螺母 M3 lock nut	x5	
x4	28. M2*3 沉头内六角螺丝 M2*3 countersunk hex screw	x5	
x1	29. M2*6 内六角螺丝 M2*6 hex screw	x5	
x2	,, (附赠)/(Additional parts)		
x2	1 模拟摄像头固定侧板 Analog camera side plate	x2	
x4	2. M2*5 沉头内六角螺丝 M2*5 countersunk hex screw	x5	
x1	¦ 3. 内六角扳手 3. Allen wrench	x1 ¦	
x1	4.M5法兰螺母 4.M5 nut	x1	
x1	5. M5*20 内六角螺丝 M5*20 hex screw	x1 :	
x1	集线管 6. Motor wire protecto	x4 ¦	
x1	7. 15*250 超纤皮电池扎带 15*250 Battery strap	x1	
x2	8. 20*250 超纤皮电池扎带 8. 20*250 Battery strap	x1	
x2	9. 电池硅胶防滑垫 9. Battery pad	x2	
x7	自锁尼龙扎带 10. Self-locking nylon zip ties	х6	
x7	道用贴纸 11. Sticker	x1 ¦	
x3	12. M2*5 内六角螺丝 12. M2*5 hex screw	x5 ¦	
x5	13. 电源线+插头 13. Power cable + plug	x1	
x10		;	

