XL10 V6

机架组装示意图

Frame Assembly Guide

1.	顶板 Top plate	x1	26. M2*8 内六角带垫螺丝 M2*8 wash head hex screw
	中板 Counter plate	x1	27. M2*8 内六角自攻螺丝 M2*8 self-tapping hex screw
	机臂 Arm	x4	28. M3*7 内六角螺丝 M3*7 hex screw
4.	底板 Bottom plate	x1	29. M3*14 内六角螺丝 M3*14 hex screw
	摄像头侧板CNC CNC camera side plate	x1	30. M3*16 内六角螺丝 M3*16 hex screw
	脚垫 Arm guard	x4	31. M2*6 内六角沉头螺丝 M2*6 countersunk hex screw
	GPS座打印件 GPS mount TPU	x1	32. M3*10 内六角带垫螺丝 M3*10 wash head hex screw
	可调节狗座底座打印件 GoPro bottom stand TPU	x1	33. M3*30 内六角螺丝 M3*30 wash screw
	摄像头硅胶侧板 Silicone camera side plate	x2	34. 格纹硅胶电池防滑垫 Battery pad
	图传天线座打印件 Antenna TPU	x1	(附赠)/(Additional parts)
	BB响/蜂鸣器打印件 Buzzer holder TPU	x1	. 集线管 1. Motor wire protector
	接收机座 Receiver mount	x1	2. 20*300超纤皮电池扎带 20*300 Battery strap
	电源线+XT60E-M 插头 XT60E-M power cable	x1	3. M5螺母 M5 nut
	固定XT60插头 Integrated XT60 battery plug mount	x1	4. 内六角扳手 A. Allen wrench
15.	9*5.4*6 双通尼龙柱 9*5.4*6 Double-pass nylon standoff	x2	5. M5*20 内六角螺丝 M5*20 hex screw
16.	M1.6 螺母 M1.6 nut	x4	6. 通用贴纸V3 Sticker V3
17.	M3*20 圆形网纹铝柱 M3*20 Al. standoff	x4	7. IPEX转SMA直头内针转接线 总长10CM IPex to SMA adapter cable 10mm
18.	MZ*20 回形网分包针	x2	1
19.	M2*25 圆形网纹铝柱 M2*25 Al. standoff	x1	
	M3*12 内六角螺丝 M3*12 hex screw	x16	
21.	M2*6 内六角螺丝 M2*6 hex screw	x2	
22.	M3 防松自紧螺母 M3 lock nut	x4	
	M1.6*16 杯头内六角螺丝 M1.6*16 socket head cap	x4	
	M2*12 内六角自攻螺丝 M2*12 self-tapping hex screw	x2	
	M2*8 内六角螺丝 M2*8 hex screw	x2	

x2

x4 x8

x4 x4 x2

x4 x4

x1

x4 x2 x1

x1 x1 x1 x1





