MATERIAL SAFETY DATA SHEET

G-11

EFFECTIVE DATE REVISED DATE TRADE NAME CHEMICAL FAMILY CHEMICAL FORMUA	December 14/ 2010 September 13, 2011 G-11 Epoxyglas Fiberglass and Epoxy Resin
SECTION II - HAZARDOUS INGREDIENTS HAZARDOUS COMPONENTS	
SECTION III - PHYSICAL DATA BOILING POINT (F) FREEZING POINT (F) VOLATILITY / VOLUME (%) MELTING POINT VAPOR PRESSURE (mmHg) VAPOR DENSITY (Air=1) SOLUBILITY IN H20 APPEARANCE / ODOR SPECIFIC GRAVITY (H20=1)	N/A <0.05% N/A N/A N/A Insoluble Yellow to light green solid 1.6
SECTION IV- FIRE AND EXPLOSION HAZARD DATA FLASH POINT LOWER FLAME POINT HIGHER FLAME POINT EXTINGUISH MEDIA FOR FIRE UNUSUAL FIRE HAZARD	Carbon dioxide, water or foam Isolate fire area and deny unnecessary entry. Fire fighters should wear positive-pressure self-contained breathing apparatus & protective clothing Dust from machining / fabrication operations may be
SECTION V- HEALTH HAZARD DATA HEALTH HAZARD	explosive in the presence of an ignition source
THRESHOLD LIMIT VALUE OVER EXPOSURE EFFECTS	Prolonged inhalation of dust can produce lung disease.
SECTION VI - REACTIVITY DATA CHEMICAL STABILITY CONDITIONS TO AVOID	Stable Protect from heat, sparks, flame and possible sources of ignition



MATERIAL SAFETY DATA SHEET

G-11

SECTION VI - REACTIVITY DATA - CONTINUED	
INCOMPATIBLE MATERIALS	Avoid contact with stron acids and bases
DECOMPOSITION PRODUCTS	Carbon dioxide, carbon monoxide, bromine and other
	hazardous gases.
HAZARDOUS POLYMERIZATIONS	Will not occur.
POLYMERIZATION AVOID	
SECTION VII - SPILL OR LEAK PROCEDURE	
FOR SPILL	Sweep up spilled material using water spray to
MARTE DIODOGAL METHOD	suppress the dust.
WASTE DISPOSAL METHOD	Dispose of in accordance with all federal, state and local regulations
	local regulations
SPECIAL VIII - SPECIAL PROTECTION	
RESPIRATORY PROTECTION	Wear a properly fidded particulate respirator approved
	for protection against dust.
VENTILATION	Use local exhaust for sawing and machining
	operations.
PROTECTIVE GLOVES	Wear gloves to protect against sharp edges and thermal
	effects when handling heated material.
EYE PROTECTION	Wear safety glasses with side shield or face shield
OTHER PROTECTIVE EQUIPMENT	Wear impervious clothing and boots for prolonged or
	repeated skin contact.
HANDLING AND STORAGE	Store in a clean, cool, ventilated area away from all
	sources of ignition
SECTION IX - SPECIAL PRECAUTIONS	
HAZARD CLASS	
DOT SHIPPING NAME	
REPORTABLE QUANITY (RQ)	
UN NUMBER NA#	
NA#	
PACKAGING SIZE	

Notes:

All information recommendations and suggestions appearing herein concerning this product are based upon data obtained from the manufacturer and/or recognized technical sources. It is the user's responsibility to determine the Safety, Toxicity and suitability of his/her own use, handling and disposal request. Since actual use by others is beyond our control, no warranty, expresses or implied, is made by Polymer Plastics Company L.C. as to effects of such use. The results to be obtained or the safety and toxicity of the product,, nor does Polymer Plastics Company L.C. assume any liability arising out of use by others of the product referred to herein. The data in this MSDS relate only to the specific material designated herein and do not relate to use in combination with any other material or in any other process.

REFERENCES: N/A = Not Applicable, N/D = Not Determined, N.D.A. = No Date Available

