### **MATERIAL SAFETY DATA SHEET**

# G-5 G-9

EFFECTIVE DATE REVISED DATE TRADE NAME	December 14, 2010 September 13, 2011 G5 / G9 Melamine
CHEMICAL FAMILY CHEMICAL FORMUA	Fiberglass, Melamine/formaldehyde Resin
SECTION II - HAZARDOUS INGREDIENTS HAZARDOUS COMPONENTS	
SECTION III - PHYSICAL DATA	
BOILING POINT (F)	
FREEZING POINT (F)	N/A
VOLATILITY / VOLUME (%) MELTING POINT	<0.05% N/A
VAPOR PRESSURE (mmHg)	N/A
VAPOR DENSITY (Air=1)	, N/A
SOLUBILITY IN H20	Insoluble
APPEARANCE / ODOR	Grayish Brown Solid
SPECIFIC GRAVITY (H20=1)	1.7
ACIDITY	
SECTION IV- FIRE AND EXPLOSION HAZARD DATA	
FLASH POINT	<00°F
LOWER FLAME POINT	
HIGHER FLAME POINT	
EXTINGUISH MEDIA	Carbon dioxide, water or foam
FOR FIRE	Isolate fire area and deny unnecessary entry. Fire
	fighters should wear positive-pressure self-contained breathing apparatus and protective clothing.
UNUSUAL FIRE HAZARD	Dust from machining / fabrication operations maybe
ONO CONCENTION LANGE	explosive in presence of an ignition source
	3, mar. 3
SECTION V- HEALTH HAZARD DATA	
HEALTH HAZARD	
THRESHOLD LIMIT VALUE	
OVER EXPOSURE EFFECTS	Prolonged inhalation of dust can produce lung disease.
	5 · · · · · · · · · · · · · · · · · · ·
SECTION VI - REACTIVITY DATA	0.11
CHEMICAL STABILITY	Stable  Protect from boot, aparks, flome and possible
CONDITIONS TO AVOID	Protect from heat, sparks, flame and possible sources of ignition.
	sources or ignition.



#### **MATERIAL SAFETY DATA SHEET**

## G-5 G-9

SECTION VI - REACTIVITY DATA - CONTINUED INCOMPATIBLE MATERIALS	Avoid contact with strong acids and bases
DECOMPOSITION PRODUCTS	Carbon dioxide, carbon monoxide, bromine and
	other hazardous gases.
HAZARDOUS POLYMERIZATIONS POLYMERIZATION AVOID	Will not occur
FOLTMERIZATION AVOID	
SECTION VII - SPILL OR LEAK PROCEDURE	
FOR SPILL	Sweep up spilled material using water spray to
WASTE DISPOSAL METHOD	suppress the dust Dispose of in accordance with all federal, state and
WAGTE BIGI COAL WETTER	local regulations
OREGIAL WILL OREGIAL PROTECTION	
SPECIAL VIII - SPECIAL PROTECTION RESPIRATORY PROTECTION	Wear a properly fitted particulate respirator for protection
NESTINATORI FROTECTION	against dust.
VENTILATION	
VENTILATION	Use local exhaust for sawing and maching operations.
PROTECTIVE GLOVES	Wear gloves to protect against sharp edges and
	thermal effects when handling heated material.
EYE PROTECTION	Wear safety glasses
OTHER PROTECTIVE EQUIPMENT	Wear impervious clothing / boots for prolonged or repeated skin contact.
HANDLING AND STORAGE	Store in a clean, cool, ventilated area away from all
	sources of ignition.
SECTION IX - SPECIAL PRECAUTIONS	
HAZARD CLASS	
DOT SHIPPING NAME	
REPORTABLE QUANITY (RQ)	
UN NUMBER NA# NA#	
INCNT	
PACKAGING SIZE	

#### Notes:

All information recommendations and suggestions appearing herein concerning this product are based upon data obtained from the manufacturer and/or recognized technical sources. It is the user's responsibility to determine the Safety, Toxicity and suitability of his/her own use, handling and disposal request. Since actual use by others is beyond our control, no warranty, expresses or implied, is made by Polymer Plastics Company L.C. as to effects of such use. The results to be obtained or the safety and toxicity of the product,, nor does Polymer Plastics Company L.C. assume any liability arising out of use by others of the product referred to herein. The data in this MSDS relate only to the specific material designated herein and do not relate to use in combination with any other material or in any other process.

**REFERENCES:** N/A = Not Applicable, N/D = Not Determined, N.D.A. = No Date Available

