US Patent & Trademark Office Patent Public Search | Text View

United States Patent

Kind Code

B2

Date of Patent

Inventor(s)

12388381

August 12, 2025

Arafat; Akm et al.

Symmetrical components domain control in a multiphase machine system

Abstract

A multiphase motor control system and method of operation. Discloses embodiments comprise receiving multiphase reference commands, transforming the multiphase reference commands into corresponding reference symmetrical components, receiving feedback information representative of multiphase drive signals in a motor, transforming the feedback information into corresponding feedback symmetrical components, generating multiphase motor control symmetrical components based on the reference symmetrical components and the feedback symmetrical components, and transforming the multiphase motor control symmetrical components into corresponding multiphase motor drive control signals.

Inventors: Arafat; Akm (Blaine, MN), Wilson; Oliver Daniel (Fridley, MN)

Applicant: Cummins Inc. (Columbus, IN)

Family ID: 1000008749192

Assignee: Cummins Inc. (Columbus, IN)

Appl. No.: 18/274567

Filed (or PCT Filed): January 14, 2022

PCT No.: PCT/US2022/012410

PCT Pub. No.: WO2022/169575

PCT Pub. Date: August 11, 2022

Prior Publication Data

Document IdentifierUS 20240113645 A1

Publication Date
Apr. 04, 2024

Related U.S. Application Data

us-provisional-application US 63146147 20210205

Publication Classification

Int. Cl.: H02P21/05 (20060101)

U.S. Cl.:

CPC **H02P21/05** (20130101);

Field of Classification Search

CPC: H02P (21/05); H02P (21/14); H02P (21/22)

USPC: 318/400.02; 318/400.01; 318/700

References Cited

U.S. PATENT DOCUMENTS

Patent No.	Issued Date	Patentee Name	U.S. Cl.	CPC
8054032	12/2010	Chakrabarti	363/133	B60L 58/20
9341660	12/2015	Wu et al.	N/A	N/A
10333445	12/2018	Pramod	N/A	H02P 21/05
10784806	12/2019	Omata	N/A	H02P 21/50
11916504	12/2023	Ling	N/A	B60L 53/22
2010/0259207	12/2009	Kitanaka	N/A	N/A
2011/0012544	12/2010	Schulz	N/A	N/A
2011/0040519	12/2010	Yeh	N/A	N/A
2013/0043816	12/2012	Welchko	N/A	N/A
2019/0006973	12/2018	Zhou et al.	N/A	N/A
2021/0028611	12/2020	Brusilowicz	N/A	N/A

FOREIGN PATENT DOCUMENTS

Patent No.	Application Date	Country	CPC
109660144	12/2018	CN	N/A

OTHER PUBLICATIONS

International Preliminary Report on Patentability received for PCT Patent Application No. PCT/US2022/012410, mailed on Aug. 17, 2023, 10 pages. cited by applicant International Search Report and Written Opinion for International patent application No. PCT/US2022/012410, filed Jan. 14, 2022, mailed Apr. 11, 2022. cited by applicant

Primary Examiner: Luo; David

Attorney, Agent or Firm: Faegre Drinker Biddle & Reath LLP

Background/Summary

CROSS-REFERENCE TO RELATED APPLICATIONS (1) The present application claims the benefit of priority to International Patent Application No. PCT/US2022/012410, filed Jan. 14, 2022, which claims the benefit of priority to U.S. Provisional Patent Application No. 63/146,147, filed Feb. 5, 2021, the contents of which are incorporated herein by reference in their entirety.

FIELD

- (1) This disclosure relates generally to multiphase machine control systems. Disclosed embodiments include a control method operating in a symmetrical components domain. BACKGROUND
- (2) Multiphase alternating current (AC) machines such as motor systems are used in a wide variety of applications including industrial settings and motor vehicles. Motor systems of these types include an AC motor and/or generator, inverter, and control system. In response to a reference or input command, the control system causes the inverter to apply power from an energy source to the motor in a controlled manner, and causes the motor to provide the commanded output. For example, in response to a torque command, the motor control system will cause the motor to deliver the requested torque at the motor output shaft.
- (3) These machines and associated systems may be characterized by certain imbalances during their operation. For example, impedance or other electrical imbalances may be present due to manufacturing variances, mutual coupling and transient operating conditions of the machines. Imbalances such as these may detrimentally constrain operating characteristics such as total output and efficiency of the machines. Known approaches to compensate for imbalances of these types include considering and averaging the imbalances on a system level. These approaches may cause undesired oscillations and instabilities, and may limit the effectiveness and response capabilities of the control system. Moreover, at any instant in time that the machine is operating near its specified performance limit, fewer than all of the machine's phases may be operating near those performance limits. The poor performing phases may limit the performance of the overall system in these situations.
- (4) There remains, therefor, a continuing need for improved multiphase machine control systems. In particular, there is a need for control systems capable of minimizing or reducing electrical leading to electromagnetic imbalances. Systems that can minimize or reduce imbalances between the multiple phases of the machines would be particularly desirable. SUMMARY
- (5) Disclosed embodiments include a multiphase machine control system including symmetrical components domain control processing. In embodiments, symmetrical components transforms are followed by dq0 (direct-quadrature-zero) reference frame transforms for the individual symmetrical components. The transforms are performed on potentially unbalanced input reference command and system feedback signal sets. The dq0 sets are compared to generate symmetrical components dq0 error sets, which may then be summed and used as the error for driving the multiphase system. (6) One example is a method for operating one or more processors of a multiphase machine (e.g.,
- motor) control system. Embodiments of the method comprise: receiving multiphase reference commands; transforming the multiphase reference commands into corresponding reference symmetrical components; receiving feedback signals representative of multiphase drive signals in a machine; transforming the feedback signals into corresponding feedback symmetrical components; generating multiphase motor control symmetrical components based on the reference symmetrical components and the feedback symmetrical components; and transforming the multiphase motor control symmetrical components into corresponding multiphase motor drive control signals.

 (7) In embodiments, the method further comprises: transforming the reference symmetrical

components from a stationary reference frame to a synchronous reference frame; and transforming the feedback symmetrical components from the stationary reference frame to the synchronous reference frame. In these embodiments, generating the multiphase motor control symmetrical components may include generating the multiphase motor control symmetrical components based on the reference symmetrical components in the synchronous reference frame and the feedback symmetrical components in the synchronous reference frame. Transforming the multiphase motor control symmetrical components in the synchronous reference frame into multiphase motor control symmetrical components in the synchronous reference frame into multiphase motor control symmetrical components in the stationary reference frame.

- (8) In any or all of the above embodiments, transforming the reference symmetrical components and the feedback symmetrical components from the stationary reference frame to the synchronous reference frame, and transforming the multiphase motor control symmetrical components in the synchronous reference frame into the stationary reference frame, may comprise direct-quadrature-zero transformations.
- (9) Any or all of the above embodiments may further include phase transforming, such as alphabeta transforming (e.g., using $\alpha\beta\gamma$ transforms), the stationary reference frame reference symmetrical components, the stationary reference frame feedback symmetrical components, and the synchronous reference frame motor control symmetrical components.
- (10) In any or all of the above embodiments, generating multiphase motor control symmetrical components may comprise summing the reference symmetrical components and the feedback symmetrical components. For example, summing the reference symmetrical components and the feedback symmetrical components may comprise subtracting the feedback symmetrical components from the reference symmetrical components.
- (11) In any or all of the above embodiments, generating the multiphase motor control symmetrical components may comprise proportionally integrating the multiphase motor control symmetrical components by a motor control algorithm.
- (12) Examples include a motor control system including one or more processors configured to perform the method of any or all of the above embodiments.
- (13) Examples include a motor system comprising a motor, an inverter, and the motor control system in accordance with any or all embodiments of the above example.
- (14) Examples include a non-transitory data storage medium programmed with instructions to perform the method of any or all of the above embodiments.

Description

BRIEF DESCRIPTION OF THE DRAWINGS

- (1) FIG. **1** is a diagrammatic illustration of a multiphase machine system, in accordance with embodiments.
- (2) FIG. **2** is a diagrammatic illustration of components of a control system, in accordance with embodiments.
- (3) FIG. **3** is a diagrammatic illustration of functional components of a control system, in accordance with embodiments.
- (4) FIG. **4** is a graph of feedback signals produced by an exemplary motor system operating in an unbalanced, open loop form, in accordance with embodiments.
- (5) FIGS. **5**A-**5**F are graphs of control parameters of an exemplary motor system operating in the open loop form corresponding to FIG. **4**, in accordance with embodiments.
- (6) FIG. **6** is a graph of feedback signals produced by an exemplary motor system operating in a balanced, closed loop form, in accordance with embodiments.
- (7) FIGS. 7A-7F are graphs of control parameters of an exemplary motor system operating in the

- closed loop form corresponding to FIG. **6**, in accordance with embodiments.
- (8) FIG. **8** is a graph of feedback signals produced by an exemplary motor system operating in a balanced, open loop form, in accordance with embodiments.
- (9) FIGS. **9**A-**9**F are graphs of control parameters of an exemplary motor system operating in the open loop form corresponding to FIG. **8**, in accordance with embodiments. DETAILED DESCRIPTION
- (10) FIG. 1 is a diagrammatic illustration of a motor system 8 including a motor control system 10 and multiphase alternating current (AC) machine such as motor 12 in accordance with embodiments. Outputs of the motor control system 10 are coupled to an inverter 14. Inverter 14 is responsive to the outputs of the motor control system 10, and controls the application of power from a source 16 to the motor 12. In addition to input multiphase control or reference commands such as a torque request, motor control system 10 receives feedback inputs from components of the system 8. In the illustrated embodiments, for example, motor control system 10 is coupled to receive feedback inputs representative of electrical operating characteristics of the motor 12 provided by devices such as current sensors 18.
- (11) As described in greater detail below, motor control system 10 processes the reference commands and feedback signals using control algorithms, including processing in a symmetrical components domain, to generate multiphase motor drive control signals or commands that cause the motor 12 to provide the commanded outputs. By this control approach including the symmetrical components domain operation, the control system 10 may command imbalances to the output of the inverter 14 that compensate for imbalances in the electrical characteristics of the motor 12 and/or create imbalances that may enhance the performance of the motor (e.g., if one or more phases is near or at a limit). The control method may also provide for reduction or addition of system harmonics in the time domain by acting on the instantaneous unbalanced measurements of the system 8. For example, harmonic content may be pre-calculated into one or more of the reference commands, thereby causing the motor 12 to be driven in a manner that produces those harmonics.
- (12) In embodiments, motor **12** is a multiphase AC electric machine having a rotor and stator windings. For example, motor **12** may be an interior permanent magnet (IPM) motor, an induction motor, or a synchronous motor. Although exemplary embodiments are described below in connection with a six-phase motor **12**, embodiments also include fewer (e.g., three-) or more (e.g., nine-) phase machines. Power source **16** can include a battery, fuel cell, conventional power grid or any other energy source suitable for the motor **12** and its application, and is a direct current (DC) source in embodiments.
- (13) Motor **12** operates in response to voltage drive signals or commands applied by the inverter **14**. In embodiments such as those described below comprising a six-phase motor **12**, inverter **14** provides voltage drive commands V.sub.A, V.sub.B, V.sub.C, V.sub.D, V.sub.E, V.sub.F (i.e., V.sub.A-F) to the motor **12**. The voltage drive commands may be pulse-width modulated (PWM) signals. The applied voltages create torque-producing currents in the windings of the motor **12** that result in rotation of the motor shaft. Inverter **14** can be of any known or otherwise conventional design. Such inverters **14** commonly include a plurality of power switches to provide the PWM drive signals.
- (14) Each of the voltage drive commands V.sub.A-F corresponds to and is associated with one of the phase windings (e.g., which may be designated A-F) of the motor 12. Accordingly, the six-phase motor 12 embodiments described herein have six voltage drive commands V.sub.A-F. In embodiments, the six-phase motor 12 may be configured to include two sets of three-phase windings (e.g., a first set of windings and a second set of windings). For purposes of convention and example, three of the voltage drive commands such as V.sub.A-C may be associated with and applied to the three windings of the first set of windings (e.g., windings A-C), and three of the voltage drive commands such as V.sub.D-F may be applied to the three windings of the second set

of windings (e.g., windings D-F).

(15) Current sensors 18 are coupled to the motor 12 and provide signals representative of the current (I) on each of the windings of the motor. In embodiments such as those described below comprising a six-phase motor **12**, current sensors **18** provide feedback signals I.sub.A, I.sub.B, I.sub.C, I.sub.D, I.sub.E, I.sub.F (i.e., I.sub.A-F) representative of the instantaneous currents on each of the windings. Current sensors **18** can be any known or otherwise conventional devices. In embodiments, current sensors 18 provide information representative of the magnitude or levels of the currents on the windings of motor **12**. With the current level information provided by current sensors 18, motor control system 10 can derive information regarding the relative phases of the signals I.sub.A-F, which will be representative of the phases of the currents in the windings of the motor **12**. In other embodiments, the current sensors **18** directly provide information regarding the phases of the motor winding currents. Yet other embodiments of the motor system 8 include sensors or other devices that provide additional or alternative information representative of electrical operating characteristics of the motor 12 (e.g., voltage feedback signals). Embodiments (not shown), may also include other sensors or devices such as an encoder, resolver or other sensor that provides information on the rotational or angular position (θ) of the shaft of motor **12**. (16) In embodiments, motor control system **10** is configured to receive multiphase control input or reference commands specifying a desired output to be produced by motor **12**. The reference commands may, for example, be representative of desired torque or speed of the motor **12**. Each reference command may correspond to one of the phases or windings of the motor **12**. In embodiments such as those described below comprising a six-phase motor 12, control system 10 may receive reference commands R.sub.A, R.sub.B, R.sub.C, R.sub.D, R.sub.E, R.sub.F (i.e., R.sub.A-F). In response to the reference commands R.sub.A-F and the feedback signals IA-F, motor control system 10 produces voltage drive control signals V.sub.a, V.sub.b, V.sub.c, V.sub.d, V.sub.e, V.sub.f (i.e., V.sub.a-f), each of which is associated with one of the windings of the motor **12**. Motor control system **10** produces the voltage drive control signals Va-f based on a control algorithm. In embodiments, motor control system 10 implements a flux-weakening (FW) and maximum-torque-per-ampere (MTPA) control algorithms to produce the voltage drive control signals. FW and MTPA algorithms are generally known, and any such conventional or otherwise known algorithm may be used by the control system **10**. The voltage drive control signals V.sub.a-f are applied to the inverter **14**, which produces the voltage drive commands V.sub.A-F in response to the voltage drive control signals.

(17) FIG. **2** is diagrammatic illustration of exemplary hardware components of the motor control system **10** in accordance with embodiments. The illustrated embodiments include a processing system **30** comprising processing components **32** and storage components **34** coupled by a bus **36**. Processing components **32** may, for example, include one or more central processing units (CPUs) **38** providing the processing functionality of the motor control system **10**. The storage components **34** may include RAM memory **40**, hard disk drive (HDD) and/or solid state drive (SSD) memory **42**, providing the information and other data storage functionality of the motor control system **10**. For example, operating system and other software used by the processing components **32** to implement the motor control methods and algorithms described herein may be stored in the storage components **34**. Components of the processing system **30** can be implemented as programmed microprocessors, application specific integrated circuits (ASICs), controllers and/or discrete circuit components. Other embodiments of the processing system **30** are implemented using other conventional or otherwise known systems or devices. The embodiments illustrated in FIG. 2 also include input/output (I/O) ports 52 through which the motor control system 10 can receive and transmit information or other data. For example, in embodiments, the current sensors **18** can be coupled to the processing components **32** through the I/O ports **52**. Reference commands such as R.sub.A-F and the drive control signals such as V.sub.a-f may be coupled to and/or from the control system **10** through the I/O ports **52**. I/O ports **52** may be coupled to a communications module (not

- shown) for sending and receiving commands, signals or messages over a network. The communication module may be capable of communications over one or more wireless or wired technologies (e.g., WiFi, Bluetooth, cellular networks, local area networks (LANs) and/or wide area networks (WANs)).
- (18) FIG. **3** is a functional diagrammatic illustration of a closed loop motor control system **10** for a six-phase motor **12** in accordance with embodiments. As described in greater detail below, the control system **10** implements motor control methods or algorithms that include operation in the symmetrical components domain. Accordingly, the control system **10** includes functionality that converts commands and signals between their then-current or instantaneous time domain values and their associated or corresponding symmetrical components domain values. In connection with a six-phase system **10**, for example, the symmetrical transformations create six balanced six-phase systems referenced to a reference phasor. A system of this type may be characterized as having ninety-degree phase shifts between each of phases A and D, phases B and E, and phases C and F. Embodiments may be defined by the following convention, where each symmetrical component includes a magnitude and an angle.
- (19) In a positive lead sequence, Plead, all phasors share the same magnitude, and the phase rotation is ABC, with these phasors separated by one-hundred and twenty degrees. The angle of the sequence is equivalent to the angle of the A phasor relative to the reference phasor. The DEF phasors are ninety degrees phase shifted from their ABC pair.
- (20) In a negative lead sequence, Nlead, all phasors share the same magnitude, and the phase rotation is ACB, with these phasors separated by one-hundred and twenty degrees. The angle of the sequence is equivalent to the angle of the A phasor relative to the reference phasor. The DFE phasors are ninety degrees phase shifted from their ACB pair.
- (21) In a positive lag sequence, Plag, all phasors share the same magnitude, and the phase rotation is DEF, with these phasors separated by one-hundred and twenty degrees. The angle of the sequence is equivalent to the angle of the D phasor relative to the reference phasor. The ABC phasors are ninety degrees phase shifted from their DEF pair.
- (22) In a negative lag sequence, Nlag, all phasors share the same magnitude, and the phase rotation is DFE, with these phasors separated by one-hundred and twenty degrees. The angle of the sequence is equivalent to the angle of the D phasor relative to the reference phasor. The ACB phasors are ninety degrees phase shifted from their DFE pair.
- (23) In a zero lead sequence, Zlead, all phasors share the same magnitude, ABC share the same angle relative to the reference phasor, and DEF are ninety degrees phase shifted from ABC.
- (24) In the zero lag sequence, Zlag, DEF share the same angle, and ABC share the same angle, which is ninety degrees phase shifted from DEF. The phasors all share the same magnitude.
- (25) As shown in FIG. **3** by step **60**, the reference commands R.sub.A-F are converted or transformed from their initial state values to their corresponding or associated three-phase, stationary reference frame symmetrical components domain values RPlead, RPlag, RNlead, RNlag, RZlead, RZlag. Conventional or otherwise known computational algorithms and approaches can be used by control system **10** to perform the symmetrical components transformation at step **60**. For example, in a six or twelve phase ninety-degree system, the instantaneous values of ABC and corresponding DEF form the real and imaginary components of three complex vectors, and a classical symmetrical transform may be performed on them directly. Position information such as that provided by a resolver may be used in connection with a three phase system to determine the angle and instantaneous power of vectors. In embodiments, for example, control system **10** may convert the individual initial state values of the reference commands to vector values, and then perform the symmetrical components transform on the vector values.
- (26) As shown by step **61**, the reference symmetrical components domain values RPlead, RPlag, RNlead, RNlag, RZlead, RZlag are phase transformed from an initial three-phase, stationary reference frame to two-phase, stationary reference frame (e.g., alpha-beta) values. In embodiments,

control system **10** performs conventional or otherwise known computational algorithms and approaches, such as alpha-beta (i.e., $\alpha\beta\gamma$ transforms) or Clarke transforms, at step **61**. (27) As shown by step **62**, the reference command symmetrical components domain values RPlead, RPlag, RNlead, RNlag, RZlead, RZlag are transformed from the stationary reference frame to a synchronous reference frame for further processing. In embodiments, control system **10** performs conventional or otherwise known computational algorithms and approaches, such as direct-quadrature-zero (i.e., dq0 transforms) to convert the reference command symmetrical components to corresponding or associated reference command synchronous frame values RPd (positive d), RPq (positive q), RNd (negative d), RNq (negative q), RZd (zero d), RZq (zero q). In embodiments, for example, control system **10** may convert vector values of the reference command symmetrical components to the dq reference frame, and then convert the vector values of the reference command symmetrical components to the individual synchronous frame reference command symmetrical values. The synchronous frame reference command symmetrical components RPd, RPq, RNd, RNq, RZd, RZq are processed by summing step **64** as described below.

- (28) As shown by step **66**, the feedback signals I.sub.A-F are converted or transformed from their instantaneous state values to their corresponding or associated three-phase stationary reference frame symmetrical components domain values IPlead, IPlag, INlead INlag IZlead, IZlag. Conventional or otherwise known computational algorithms and approaches, including those described above, can be used by control system **10** to perform the symmetrical components transformation at step **66**. In embodiments, for example, control system **10** may convert the instantaneous state values of the feedback signals to vector values, and then perform the symmetrical components transform on the vector values.
- (29) As shown by step **67**, the feedback symmetrical components domain values IPlead, IPlag, INlead, INlag, IZlead, IZlag are phase transformed from an initial three-phase, stationary reference frame to two-phase, stationary reference frame (e.g., alpha-beta) values. In embodiments, control system **10** performs conventional or otherwise known computational algorithms and approaches, such as alpha-beta or Clarke transforms, at step **67**.
- (30) As shown by step **68**, the feedback symmetrical components domain values IPlead, IPlag, INlead, INlag, IZlead, IZlag are transformed from the stationary reference frame to the synchronous reference frame for further processing. In embodiments, control system **10** performs conventional or otherwise known computational algorithms and approaches, such as dq0 transforms, to convert the feedback information symmetrical components to corresponding or associated synchronous frame values IPd (positive d), IPq (positive q), INd (negative d), INq (negative q), IZd (zero d), IZq (zero q). In embodiments, for example, control system **10** may convert vector values of the feedback information symmetrical components to the dq reference frame, and then convert the vector values of the feedback information symmetrical values. In embodiments, an angle value, such as for example that provided by a resolver, may be used in connection with the conversion of the vector values of the feedback information symmetrical components to the associated synchronous reference frame values. The synchronous frame feedback symmetrical components IPd, IPq, INd, INq, IZd, IZq are processed by summing step **64**.
- (31) At step **64** the control system **10** performs a logical function such as a summing operation to combine the synchronous frame reference command symmetrical components RPd, RPq, RNd, RNq, RZd, RZq and the synchronous frame feedback information symmetrical components IPd, IPq, INd, INq, IZd, IZq. The control system **10** thereby generates synchronous frame control symmetrical components CPd, CPq, CNd, CNq, CZd, CZq. In embodiments, at step **64** the control system **10** subtracts the feedback information symmetrical components from the reference command symmetrical components to produce the synchronous frame control symmetrical components in a form that will compensate for electrical and/or other imbalances in the motor **12**

- and/or other components of system **8**. By this action, in embodiments the negative and zero synchronous frame control symmetrical components CNd, CNq, CZd, CZq, which represent complex outputs, may be forced to zero, while the positive synchronous frame drive command symmetrical components CPd, CPq, which represent a real output, may have a non-zero value. An objective is to create an imbalance that will interact with system imbalances to achieve a desired state. In embodiments, the desired state may be no resulting imbalances. In other embodiments an objective may be to provide certain imbalances.
- (32) At step **70** the control system **10** performs proportional-integral (PI) control based the synchronous frame control symmetrical components CPd, CPq, CNd, CNq, CZd, CZq. As described above, conventional or otherwise known control algorithms such as FW and MTPA algorithms can be performed at step **70**. By these actions the control system **10** operates in the symmetrical components domain to generate synchronous frame drive command symmetrical components DPd, DPq, DNd, DNq, DZd, DZq representative of the desired voltage drive control signals V.sub.a-f.
- (33) At steps **72**, **73** and **74** the control system **10** coverts the synchronous frame drive command symmetrical components DPd, DPq, DNd, DNq, DZd, DZq to the corresponding instantaneous drive control signals V.sub.a-f. In the illustrated embodiments, for example, at step **72** the control system **10** converts or transforms the synchronous frame drive command symmetrical components DPd, DPq, DNd, DNq, DZd, DZq to their corresponding two-phase stationary reference frame drive command symmetrical components values DPlead, DPlag, DNlead, DNlag, DZlead, DZlag. Conventional or otherwise known computational approaches or algorithms, including those such as dq0 transforms described above, can be used by control system **10** in connection with step **72**. In embodiments, for example, control system **10** may convert the synchronous frame drive command symmetrical components to vector values, and then perform the symmetrical components transform on the vector values. An angle value can be used in connection with the conversion of the vector values of the drive command symmetrical components to the associated stationary reference frame values.
- (34) As shown by step **73**, the stationary reference frame drive command symmetrical components domain values DPlead, DPlag, DNlead, DNlag, DZlead, DZlag are phase transformed from the two-phase, stationary reference frame (e.g., alpha-beta) values to corresponding three-phase, stationary reference frame values. In embodiments, control system **10** performs conventional or otherwise known computational algorithms and approaches, such as alpha-beta or Clarke transforms, at step **73**.
- (35) At step **74**, the three-phase stationary frame drive command symmetrical components are converted or transformed to the corresponding or associated instantaneous drive control signals V.sub.a-f. Conventional or otherwise known computational approaches or algorithms, including those described above, can be used by control system **10** in connection with step **74**. In embodiments, for example, control system **10** may convert vector values of the stationary frame drive command symmetrical sequences to unbalanced phasors, and then convert the vector values of the unbalanced phasors to the individual instantaneous drive control signals.
- (36) Embodiments of the motor systems **8** configured with control systems **10** of the types described herein have demonstrated enhanced balanced, closed loop operation in environments that would otherwise have exhibited unbalances. FIG. **4** is a graph of feedback signals I.sub.A-F produced by an exemplary motor system **8** operating in open loop form and representative of the phases A-F, respectively. The unbalanced nature of the motor system **8** is evidenced by the unsymmetrical nature of the amplitudes and phases of the feedback signals. Measured control parameters of the system **8** in the open loop, unbalanced form corresponding to FIG. **4** are shown in FIGS. **5**A-**5**F. FIG. **5**A is a graph of the positive d feedback information symmetrical component IPq; FIG. **5**C is a graph of the negative d feedback information symmetrical component INd; FIG. **5**D is a

graph of the negative q feedback information symmetrical component INq; FIG. **5**E is a graph of the zero d feedback information symmetrical component IZd; and FIG. **5**F is a graph of the negative q feedback information symmetrical component IZq.

- (37) FIG. **6** is a graph of feedback signals I.sub.A-F produced by an exemplary motor system **8** operating in closed loop form with the symmetrical components domain control methodology described herein, and representative of the phases A-F, respectively. The balanced nature of the motor system **8**, and the use of the control algorithms disclosed herein, are evidenced by the symmetrical nature of the amplitudes and phases of the feedback signals. Measured control parameters of the system **8** in the closed loop, balanced form corresponding to FIG. **6** are shown in FIGS. **7A-7F**. FIG. **7A** is a graph of the positive d feedback information symmetrical component IPd; FIG. **7B** is a graph of the negative d feedback information symmetrical component INd; FIG. **7D** is a graph of the negative q feedback information symmetrical component INq; FIG. **7E** is a graph of the zero d feedback information symmetrical component IZd; and FIG. **7F** is a graph of the negative q feedback information symmetrical component IZd; and FIG. **7F** is a graph of the negative q feedback information symmetrical component IZd; and FIG. **7F** is a graph of the negative q feedback information symmetrical component IZd; and FIG. **7F** is a graph of the negative q feedback information symmetrical component IZd; and FIG. **7F** is a graph of the negative q feedback information symmetrical component IZd;
- (38) FIG. 8 illustrates, for purposes of reference and example, a graph of feedback signals I.sub.A-F representative of the winding phases A-F, respectively, produced by an exemplary motor system 8 operating in open loop form without the symmetrical components domain control methodology described herein, but when the system is balanced. The balanced nature of the motor system 8 is evidenced by the symmetrical nature of the amplitudes and phases of the feedback signals. Measured control parameters of the system 8 in the open loop, balanced form corresponding to FIG. 8 are shown in FIGS. 9A-9F. FIG. 9A is a graph of the positive d feedback information symmetrical component IPd; FIG. 9C is a graph of the negative d feedback information symmetrical component INd; FIG. 9D is a graph of the negative q feedback information symmetrical component INq; FIG. 9E is a graph of the zero d feedback information symmetrical component IZd; and FIG. 9F is a graph of the negative q feedback information symmetrical component IZd; and FIG. 9F is a graph of the negative q feedback information symmetrical component IZd.
- (39) It is to be understood that the above description is intended to be illustrative, and not restrictive. Many other embodiments will be apparent to those of skill in the art upon reading and understanding the above description. For example, it is contemplated that features described in association with one embodiment are optionally employed in addition or as an alternative to features described in or associated with another embodiment. The compensation approaches described herein can be incorporated into motors having fewer or greater numbers of phases. The scope of the invention should, therefore, be determined with reference to the appended claims, along with the full scope of equivalents to which such claims are entitled.

Claims

- 1. A method for operating one or more processors of a multiphase motor control system, comprising: receiving multiphase reference commands; transforming the multiphase reference commands into corresponding reference symmetrical components; receiving feedback information representative of multiphase drive signals in a motor; transforming the feedback information into corresponding feedback symmetrical components; generating multiphase motor control symmetrical components based on the reference symmetrical components and the feedback symmetrical components; and transforming the multiphase motor control symmetrical components into corresponding multiphase motor drive control signals.
- 2. The method of claim 1 wherein: transforming the multiphase reference commands comprises: transforming the reference commands into reference symmetrical components in a stationary reference frame; and transforming the stationary reference frame reference symmetrical

components into a synchronous reference frame; transforming the feedback information comprises: transforming the feedback information into feedback symmetrical components in the stationary reference frame; and transforming the stationary reference frame feedback symmetrical components into the synchronous reference frame; generating the multiphase motor control symmetrical components in the synchronous reference frame based on the reference symmetrical components in the synchronous reference frame and the feedback symmetrical components in the synchronous reference frame; and transforming the multiphase motor control symmetrical components comprises: transforming the synchronous reference frame motor control symmetrical components into the stationary reference frame; and transforming the stationary reference frame motor control symmetrical components into the multiphase motor drive control signals.

- 3. The method of claim 2 wherein transforming the reference symmetrical components and the feedback symmetrical components from the stationary reference frame into the synchronous reference frame, and transforming the multiphase motor control symmetrical components from the synchronous reference frame into the stationary reference frame, comprises direct-quadrature-zero transformations.
- 4. The method of claim 3 and further including phase transforming (e.g., alpha-beta transforming) the stationary reference frame reference symmetrical components, the stationary reference frame feedback symmetrical components, and the synchronous reference frame motor control symmetrical components.
- 5. The method of claim 2 and further including phase transforming (e.g., alpha-beta transforming) the stationary reference frame reference symmetrical components, the stationary reference frame feedback symmetrical components, and the synchronous reference frame motor control symmetrical components.
- 6. The method of claim 1 wherein generating multiphase motor control symmetrical components comprises summing the synchronous reference frame reference symmetrical components and the synchronous reference frame feedback symmetrical components.
- 7. The method of claim 6 wherein summing the synchronous reference frame reference symmetrical components and the synchronous reference frame feedback symmetrical components comprises subtracting the synchronous reference frame feedback symmetrical components from the reference symmetrical components.
- 8. The method of claim 1 wherein generating the multiphase motor control symmetrical components further comprises PID (proportional, integral, differential) processing the synchronous reference frame multiphase motor control symmetrical components by a motor control algorithm.
- 9. The method of claim 1 for a six-phase motor.
- 10. A motor control system including one or more processors configured to: receive multiphase reference commands; transform the multiphase reference commands into corresponding reference symmetrical components; receive feedback information representative of multiphase drive signals in a motor; transform the feedback information into corresponding feedback symmetrical components; generate multiphase motor control symmetrical components based on the reference symmetrical components and the feedback symmetrical components; and transform the multiphase motor control symmetrical components into corresponding multiphase motor drive control signals. 11. The motor control system of claim 10 wherein the one or more processors are configured to:
- transform the multiphase reference commands by steps comprising: transforming the reference commands into reference symmetrical components in a stationary reference frame; and transforming the stationary reference frame reference symmetrical components into a synchronous reference frame; transform the feedback information by steps comprising: transforming the feedback information into feedback symmetrical components in the stationary reference frame; and transforming the stationary reference frame feedback symmetrical components into the synchronous reference frame; generate the multiphase motor control symmetrical components by

steps comprising generating the multiphase motor control symmetrical components in the synchronous reference frame based on the reference symmetrical components in the synchronous reference frame and the feedback symmetrical components in the synchronous reference frame; and transform the multiphase motor control symmetrical components by steps comprising: transforming the synchronous reference frame motor control symmetrical components into the stationary reference frame motor control symmetrical components into the multiphase motor drive control signals.

- 12. The motor control system of claim 11 wherein the one or more processors are configured to transform the reference symmetrical components and the feedback symmetrical components from the stationary reference frame into the synchronous reference frame, and transform the multiphase motor control symmetrical components from the synchronous reference frame into the stationary reference frame, by steps comprising direct-quadrature-zero transformations.
- 13. The motor control system of claim 10 and further comprising a motor and an inverter coupled to the motor control system.
- 14. A tangible, non-transitory computer-readable medium programmed with instructions to operate a multiphase motor that, when executed by one or more processors of a computer system, cause the computer system to: receive multiphase reference commands; transform the multiphase reference commands into corresponding reference symmetrical components; receive feedback information representative of multiphase drive signals in a motor; transform the feedback information into corresponding feedback symmetrical components; generate multiphase motor control symmetrical components based on the reference symmetrical components and the feedback symmetrical components; and transform the multiphase motor control symmetrical components into corresponding multiphase motor drive control signals.
- 15. The tangible, non-transitory computer-readable medium of claim 14, wherein the instructions cause the computer system to: transform the multiphase reference commands by steps comprising: transforming the reference commands into reference symmetrical components in a stationary reference frame; and transforming the stationary reference frame reference symmetrical components into a synchronous reference frame; transform the feedback information by steps comprising: transforming the feedback information into feedback symmetrical components in the stationary reference frame; and transforming the stationary reference frame feedback symmetrical components into the synchronous reference frame; generate the multiphase motor control symmetrical components in the synchronous reference frame based on the reference symmetrical components in the synchronous reference frame and the feedback symmetrical components in the synchronous reference frame motor control symmetrical components by steps comprising: transforming the synchronous reference frame motor control symmetrical components into the stationary reference frame; and transforming the stationary reference frame motor control symmetrical components into the multiphase motor drive control signals.
- 16. The tangible, non-transitory computer-readable medium of claim 15, wherein the instructions cause the computer system to transform the reference symmetrical components and the feedback symmetrical components from the stationary reference frame into the synchronous reference frame, and transform the multiphase motor control symmetrical components from the synchronous reference frame into the stationary reference frame, by steps comprising direct-quadrature-zero transformations.
- 17. The tangible, non-transitory computer-readable medium of claim 16, wherein the instructions cause the computer system to phase transform (e.g., alpha-beta transform) the stationary reference frame reference symmetrical components, the stationary reference frame feedback symmetrical components, and the synchronous reference frame motor control symmetrical components.