Motor Controls Harness color code

T pec	15 wire harness with no black tape marker
NO TRANSPORT	
- 1254 M	
v Nov Hoos	Do Red/Black Tr
2	D, Blue/ Black Tr
3	Dz Green/ White Tr
4	D3 Blue - 100 15 56
5	Dy Orange Jo PR waist
6	D5 Green/Black Tr = By 12 +5V)
7	Do Blue / White Tr = 100 5 100 Sensor
8	D7 Orange/BlackTr
14	Red-Installed Power supply on lower board
16	Signal and Black/White Tr
13	Waist-Right Red / WhiteTr
	wrist-Left white/Black Tr
(Torso) waist sensor-same harness
Contraction of the Contraction o	+5V white -11
9	Gnd Black -9
10	Pin 38 on ADC Green -10