

TASK 2: POSITIONING MONITORING SYSTEM

NAME: HARSHIT SINGH PS.NO. 20368671

DRC:



WIRING DIAGRAM



PCB DESIGN

