

Buck Converter

$V_{in_min} = 9.0V$	$V_{in_max} = 52.0V$	$V_{in} = 52.0V$
$V_{out} = 5.0V$	$I_{out} = 5.0A$	$f = 100.0kHz$
$L = 25.41\mu H$	$\Delta I_L \text{ for } V_{in_max} = 2.0A$	

