

Practice: Checking Data Quality with Summary Statistics and Graphs

In this practice, you use the file **Messy Data 2.jmp** to identify data quality issues using summary statistics and graphs. This data table has seven variables: **acceptable?**, **lot number**, **unit number**, **location**, **humidity**, **voltage**, and **density**.

- 1. Use the Columns Viewer under the **Cols** menu and the **Distribution platform** to identify evidence of the following issues:
 - incorrect formatting
 - o incomplete data,
 - o missing data, and
 - dirty or messy data.
- 2. For each variable, what do you learn?

acceptable?: This variable is missing eight values.

lot number: This variable is coded as numeric/continuous data. It should be nominal.

unit number: There are six units, and the most frequently used are units 2 and 9.

location: There are nine locations and four missing values. This variable is messy. The names need to be cleaned up.

humidity: This variable is missing four values. **voltage**: There are 88 missing values for voltage. **density**: All but five of the values are the same (40).

Hide Solution

Statistical Thinking for Industrial Problem Solving

Copyright © 2020 SAS Institute Inc., Cary, NC, USA. All rights reserved.

Close