

## **DATA LOGGER**


## Step 1






Check The wire, battery and POLY CIRCUIT BORAD (PCB)

## Step 3



Check the Connections of wires of sensors

Step 4





Clip the Hose Clamp into the Mounting of the Logger with help of screwdriver.