

DOCUMENT TYPE: Internal Email (Contractor, internal correspondence)
DATE: 15-Apr-2019 FROM: Contractor, Site Geotechnical Engineer TO:
Contractor, Project Manager SUBJECT: RE: P-42 excavation - soft pocket
observed

FYI - during our own excavation monitoring at P-42 last week we noticed the base strata looked softer than the original GI report suggested, similar to what we saw at P-38 last year. Didn't want to flag it formally yet since the client's geotech consultant hasn't done their supplementary boring here. Will keep an eye on it.

[This email is dated 15-Apr-2019, several weeks before the formal Geotechnical Report GEO-DMV7-P42-011 dated 02-May-2019, and suggests the Contractor's own team privately observed the soil condition before the "official" trigger event.]