Total No. of Questions:	8]	
--------------------------------	---	---	--

SEAT No.:		
[Total	No. of Pages :	2

P2805

[6003]-530


T.E. (Robotics & Automation Engineering) FLEXIBLE MANUFACTURING SYSTEMS (2019 Pattern) (Semester - II) (311510 (A))

Time: 2½ Hours] [Max. Marks: 70 Instructions to the cardidates:

- 1) Solve Q.1 or Q.2, Q.3 or Q.4, Q.5 or Q.6, Q.7 or Q.8.
- 2) Figure to the right indicates full marks.
- 3) Neat Diagram must be drawn wherever necessary.
- 4) Assume suitable data, if necessary.
- 5) Use of Logarithmic Table, Slide rule is Electronic pocket calculator is allowed.
- Q1) a) What are the basic components of the NC system and explain the function of each component? [9]
 - b) Describe various G and M codes used in CNC machines. [9]

OR

Q2) a) Prepare part programming of following component



All dimensions in mm.

- b) Discuss the several word functions in Numerical Control systems. Discuss the advantages of DNC over NC/CNC [9]
- Q3) a) Explain with block diagram the main elements of CIM system. [9]
 - b) Explain about computer aided process planning (CAPP) [8]

OR

Q4)	a)	What is computer aided inspection (CAI) and how can we control qu	uality
		with the help of CAI?	[9]
	b)	What is a material requirement planning? Explain the various inp	uts to
		the MRP system?	[8]
<i>Q5</i>)	a)	What are the different types of material handling equipment?	[9]
	b)	What are the components of the AS/RS system?	[9]
		OR OR	
Q6)	a)		
	1 \	Also describe the components.	[9]
	b)	What are different types of AGV Explain with their principle of working	1g.[9]
Q 7)	a)	What are the different types of tool strategies? Explain Each.	[9]
	b)	Explain the term Tool Monitoring and fault Detection.	[8]
Q 8)	a)	What do you know about tool Management? Write note on tool I	Room
		Service and Tool Allocation.	[9]
	b)	Draw and explain block diagram offered detection in vibration.	[8]
		Draw and explain block diagram offered detection in vibration.	
		60° v	