

For internal use only

Prepared for: Siemens BT

Prepared by: LMtec swiss GmbH

Guggenbühlstrasse 22

CH-8586 Erlen

www.lmtec-group.com

E-Mail: lmtec@lmtec.ch

Phone: +41 (0)71 545 07 60

Fax: +41 (0)43 260 92 60

Use of this document shall be expressly limited to the purpose of Siemens BT. The information set forth in this document may only be disclosed to Customer's employees working in the Customer organization to which this document is provided.



For internal use only

Document Information

Project Name:	Revisionierung von Common Co	omponents	
Prepared by:	Samuel	Version no:	1-0
Title:	PLM Consultant	Version date:	02.06.2017

Distribution List

Company	Persons
Siemens BT	Dirk Heuer, Claus Franz, Patrick Hepp

Change History

Ver. no.	Date	Author	Reason	Description
1-0	04.05.2017	S. Wetter	Initial Version	-



For internal use only

Table of Contents


1	Initi	ial Situation/Problems	4			
	1.1	Situation	4			
	1.2	Problems	4			
	1.3	Goals	4			
2	Solution					
3	Test	t-Cases	6			
	3.1	Test-Steps	6			
		Expected Results				

For internal use only

1 Initial Situation/Problems

1.1 Situation

At Siemens BT the Common Components have 3D-DirectModels (JT-Files) attached:



1.2 Problems

If a Common Component gets revised, the new revision has no 3D-DirectModel related. This means it must be attached manually.

But instead another problem popped up. The revision name of the new 3D-DirectModel gets not updated (e.g. A5Q00004709-A \rightarrow A5Q00004709-B).


1.3 Goals

The 3D-DirectModel should be automatically copied as object when revising a Common Component. This should be the default selected copy option.


For internal use only

2 Solution

During the evaluation of the problem it was found, that the behavior of the 3D-DirectModels on revising is already correct and for that topic no changes are required.



To solve this issue with the wrong revision naming of the 3D-DirectModel the appropriate site preference "TCPB_CopyDataSetNames" of PLM-Easy-Toolbox must be modified (adding new value for DirectModel.IMAN_rendering):






3 Test-Cases

3.1 Test-Steps

- 1. Search an existing Common Component in Teamcenter
- 2. Start Workflow "BT7_ReviseCommonComp" on revision



3. Revise the Common Component

3.2 Expected Results

The new revision of Common Component has a related 3D-DirectModel attached and its revision name is correct:

```
> SA5Q00004709 | A | CAP_CER_ML_10u_+-10%_25V_1210_SMD ! SA5Q00004709 | B | CAP_CER_ML_10u_+-10%_25V_1210_SMD 
> A5Q00004709-B
> A5Q00004709-B
> Concerned
```