

SIA Supplier Quality Program

Three-day virtual requirements completion and solution design agenda

Workshop purpose

This workshop will complete the detailed requirements for Product Management, Pilot Part Data, PPAP, and Supplier Scorecard. Sessions build on decisions made in earlier workshops and focus on unresolved data, workflow, integration, security, reporting, and user-experience requirements needed to prepare the design documentation for review and approval.

DAY 1	DAY 2	DAY 3
Product Management and Pilot Part Data	Production Part Approval Process	Supplier Scorecard and Design Completion
Part and supplier data; inspection specifications; ECS controls; sample-level inspections, ownership, execution, and NCR initiation.	PPAP scope and warrant; element workflows; evidence reuse; approvals; integrations; reporting, scheduling, and certification.	KPI catalogue and sources; monthly compilation, review, publication, dashboards, unresolved dependencies, and next steps.

Daily format

Each virtual session runs from 9:30 a.m. to 4:30 p.m. Eastern Time, with a 45-minute lunch from approximately 12:00 to 12:45 p.m., a 10-minute morning break, a 10-minute afternoon break, and a facilitated daily closeout.

SCOPE	Detailed design for Product Management, Pilot Part Data, PPAP, and Supplier Scorecard. Accepted ADRs are treated as design constraints; proposed decisions and documented follow-ups are confirmed during the workshop.
--------------	---

Product Management and Pilot Part Data

Master data and inspection design foundation

TIME	SESSION	INTENDED OUTCOMES
9:30-9:45	Workshop opening	Introductions, objectives, scope boundaries, decision approach, prior ADR status, expected outputs, and virtual working conventions.
9:45-10:35	Part data and integration foundation	Confirm production and service-part sources, identifiers, refresh behavior, field ownership, update precedence, local exceptions, and data-quality controls.
10:35-10:45	Morning break	
10:45-11:25	Supplier, facility, depot, and part relationships	Define relationship types, authoritative sources, active dates, supplier shortlisting, depot enrichment, and handling of manufacturing and sequencing providers.
11:25-12:00	Inspection specification governance	Confirm specification keys, attribute types, tolerances, instructions, images, QMS boundaries, versioning, correction, review, release, and migration rules.
12:00-12:45	Lunch	
12:45-1:40	ECS orchestration and downstream decisions	Define BOMEX/ECS staging, ownership, PPAP and specification checkpoints, not-applicable rules, duplicate handling, traceability, and completion controls.
1:40-2:25	Pilot Part Data structure	Define inspection requests, samples, attribute results, evidence, sample creation, lifecycle context, and links to parts, suppliers, events, and released specifications.
2:25-2:35	Afternoon break	
2:35-3:25	Inspection execution and disposition	Confirm response controls, tolerances, pass/fail logic, overall disposition, images, connected-device layout, offline fallback, and reconciliation.
3:25-4:10	Inspection planning, ownership, and NCR initiation	Define purpose applicability, frequency plans, QC New Model and SQA routing, handover, failure-to-NCR criteria, inherited data, evidence, and subtype behavior.
4:10-4:30	Day 1 closeout	Review decisions, proposed ADR confirmations, open questions, source-data actions, owners, and dependencies for PPAP design.

Production Part Approval Process

Drawing-scoped PPAP design, workflow, integration, and reporting

TIME	SESSION	INTENDED OUTCOMES
9:30-9:45	Day 2 opening	Review Day 1 dependencies and confirm priorities for detailed PPAP design.
9:45-10:35	PPAP scope and integrated warrant	Confirm drawing-scoped parent design, selected part numbers, supplier scope, warrant fields, part-level mass data, validation, and controlled scope changes.
10:35-10:45	Morning break	
10:45-12:00	PPAP elements and routing	Define the element catalogue, reusable routing patterns, internal and supplier responsibilities, visibility, not-required treatment, rejection, correction, resubmission, and overall completion.
12:00-12:45	Lunch	
12:45-1:35	Evidence versioning and inspection linkage	Define element lineage, approved evidence reuse, current baseline views, file retention, and links to PPAP sample inspections and frozen specification revisions.
1:35-2:25	Roles, approvals, and concurrent PPAPs	Confirm supplier-depot coordinator roles, missing-role controls, reassignment, escalation, criticality-based group-leader approval, and human sequencing of overlapping PPAPs.
2:25-2:35	Afternoon break	
2:35-3:20	BOMEX initiation and integration	Define payload, authoritative keys, drawing access, revision and duplicate behavior, requirement rules, source-linked draft creation, and release confirmation ownership.
3:20-4:10	Scheduling, reporting, and approval output	Confirm due-date inputs, shipment-event exceptions, notifications, dashboard filters, aging thresholds, shared-role attribution, and approval-certificate content and supersession.
4:10-4:30	Day 2 closeout	Review PPAP decisions, unresolved integration questions, required samples, assigned actions, and scorecard data dependencies.

Supplier Scorecard and Design Completion

Monthly performance governance followed by cross-application completion

TIME	SESSION	INTENDED OUTCOMES
9:30-9:45	Day 3 opening	Review outstanding items and confirm the scorecard and cross-application priorities for the final day.
9:45-10:35	KPI catalogue and governance	Define initial KPIs, data types, applicability, effective versions, formulas, requiredness, ownership, aggregation behavior, and not-applicable treatment.
10:35-10:45	Morning break	
10:45-12:00	KPI sources and calculations	Map automated and manual sources; confirm PPM numerator and consumption denominator, NCR exclusions, PPAP timeliness, other source measures, refresh timing, and quality controls.
12:00-12:45	Lunch	
12:45-1:45	Monthly compilation and review workflow	Define scorecard creation, contributor tasks, entry cutoff, missing-value rules, exceptions, reminders, escalation, internal review, silence-as-consent, and freeze behavior.
1:45-2:25	Hierarchy and supplier publication	Confirm facility and depot scorecards, parent-company rollups, publication timing, global versus sub-batch release, notifications, supplier comments, and access scope.
2:25-2:35	Afternoon break	
2:35-3:20	Scorecard experience and reporting	Define contributor, coordinator, reviewer, and supplier views; completion dashboard; trend presentation; portal summaries; record drill-through; and Power BI boundaries.
3:20-4:05	Cross-application design completion	Resolve remaining relationships across Product Management, inspections, PPAP, NCR, supplier hierarchy, and scorecard data; confirm assumptions and scope issues.
4:05-4:30	Final workshop closeout	Confirm decisions, ADR updates, action owners, due dates, design-document deliverables, review sequence, approval process, and readiness for detailed design.

Outputs and preparation

EXPECTED OUTPUTS
Confirmed detailed requirements and decisions; validation or revision of proposed ADRs; an action and open-question register; inputs for logical object models, field lists, workflow diagrams, integration mappings, security design, reports, mockups, and an agreed documentation review and approval plan.
RECOMMENDED PARTICIPANTS
Business owners and key users for Product Management, Pilot Part Data, PPAP, and Supplier Scorecard; New Model and SQA representatives; supplier-quality and inspection users; Procurement and supplier-management representatives; SIA IT, integration, PartsMaster, BOMEX, and reporting representatives; and the Intellex/Summit solution team.
RECOMMENDED PREPARATION
Current part, drawing, ECS, supplier, facility, and depot data examples; existing inspection spreadsheets and images; PPAP element and routing examples; role and approval matrices; representative scorecards and KPI definitions; parts-consumption, PIR, scrap, CAPA, PPAP, warranty, delivery, and safety source details; integration specifications; and known technical constraints.
SCOPE CONTROL
Accepted ADRs are baseline design constraints and will not be reopened unless new evidence shows a material conflict. Proposed ADRs and documented follow-ups are decision topics. New requirements outside Product Management, Pilot Part Data, PPAP, Supplier Scorecard, and their necessary integration boundaries will be recorded for separate scope assessment.