



Maritime &
Coastguard
Agency

Guidance

Safety Bulletin 28 - JRC navigation and communication equipment

Published 22 April 2022

Contents

Summary of issue

Actions to take

Legal requirements

Related documents

Annex 1



© Crown copyright 2022

This publication is licensed under the terms of the Open Government Licence v3.0 except where otherwise stated. To view this licence, visit nationalarchives.gov.uk/doc/open-

[government-licence/version/3](#) or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or email: psi@nationalarchives.gov.uk.

Where we have identified any third party copyright information you will need to obtain permission from the copyright holders concerned.

This publication is available at <https://www.gov.uk/government/publications/safety-bulletin-28-jrc-navigation-and-communication-equipment/safety-bulletin-28-jrc-navigation-and-communication-equipment>

Summary of issue

The Maritime and Coastguard Agency would like to make operators aware that products with JRC Global Positioning System (GPS) chips for position or UTC (Coordinated Universal Time), may produce an error on May 15th 2022 at 00:00 AM (UTC). The problem affects products listed in Annex 1 and includes navigation and communication equipment.

This may result in:

- Loss of scheduled transmission; LRIT and VMS transmission functions.
- Incorrect date in the transmitted data and log function.
- Inmarsat network registration and communication failure.

Actions to take

1. Check that your JRC equipment is listed in Annex 1.
2. If it is listed, see the [JRC website](http://www.jrc.co.jp/eng/about/news/2021/1224-1.html)
(<http://www.jrc.co.jp/eng/about/news/2021/1224-1.html>)

Legal requirements

Owners are responsible for the correct operation and maintenance and should contact JRC for advice.

Related documents

Annex 1

Affected models:

Equipment Type	Models	Serial Numbers	Notice
Inmarsat-C	JUE-85	GR10251 – GR23738	Scheduled transmission, LRIT and VMS transmission functions are stopped. The date in the transmitted data and the log function returns to the starting date.
Inmarsat mini-C	JUE-95SA	GR10051 – GR23188	Scheduled transmission, LRIT and VMS transmission functions are stopped. The date in the transmitted data and the log function returns to the starting date.
Inmarsat mini-C	JUE-95LT	GR11703 – GR23598	Scheduled transmission, LRIT and VMS transmission functions are stopped. The date in the transmitted data and the log function returns to the starting date.
Inmarsat mini-C	JUE-95VM	GR10001 – GR23593	Scheduled transmission, LRIT and VMS transmission functions are stopped. The date in the transmitted data and the log function returns to the starting date.
Inmarsat Fleet	JUE-250	All	The registration process to the Inmarsat network fails and communication becomes

Equipment Type	Models	Serial Numbers	Notice
Broadband FB250			impossible. The date of the internal clock and log function of the device returns to the starting date.
GPS Navigator	JLR-7700MKII	After KE47190	Note that time and date will go back to the starting date (September 29, 2002) when a master-reset of equipment or a battery replacement is carried out after rollover day.
GPS Receiver	JLR-4330	After KE54239	Note that time and date will go back to the starting date (September 29, 2002) when a master-reset of equipment or a battery replacement is carried out after rollover day.
GPS Receiver	JLR-4331	After KE50479	Note that time and date will go back to the starting date (September 29, 2002) when a master-reset of equipment or a battery replacement is carried out after rollover day.



OGL

All content is available under the [Open Government Licence v3.0](#), except where otherwise stated



© Crown copyright