Series

Showing 4569 series with status: 'new', 'in progress', 'incomplete' reset filters

« 1 2 ... 46 »

ID	Series	Tests	Status	Patches	Submitter	Reviewer	Upda
55308	drm/i915: Pull all the reset functionality together into i915_reset.c (/series/55308/)	warning	New	1	Chris Wilson	None	2019-
55340	series starting with [1/4] drm/i915/vbt: Add 'tp4' to varibles holding TP2/3/4 PSR wakeup time (/series/55340/)		New	4	Souza, Jose	None	2019-
55327	Timing issues between ALSA and i915 drivers (/series/55327/)		New	1	Takashi lwai	None	2019-
55232	drm: Split out drm_probe_helper.h (/series/55232/)		New	1	Daniel Vetter	None	2019-
51408	Add support for Gen 11 pipe color features (/series/51408/)		New	6	Shankar, Uma	None	2019-
55311	drm/i915: Limit the for_each_set_bit() to the valid range (/series/55311/)		New	1	Chris Wilson	None	2019-
54280	drm/i915/perf: add OA interrupt support (/series/54280/)		New	7	Lionel Landwerlin	None	2019-
55281	drm/i915: switch to kernel fixed size types (/series/55281/)	warning	New	17	Jani Nikula	None	2019-
54917	drm/i915/query: Split out query item checks (/series/54917/)	success	New	1	Abdiel Janulgue	None	2019-
55265	drm/i915: Move intel_execlists_show_requests() aside (/series/55265/)	failure	New	1	Chris Wilson	None	2019-
55203	drm/i915: Pass down rc in intel_encoder->compute_config() (/series/55203/)	failure	New	1	Lyude Paul	None	2019-
55249	Add uAPI to support ICL VME hardware for new media-driver (/series/55249/)	failure	New	6	Joonas Lahtinen	None	2019-
51362	drm/i915/userptr: Avoid struct_mutex recursion for mmu_invalidate_range_start (/series/51362/)	failure	New	1	Chris Wilson	None	2019-
46547	drm/i915: Differentiate between ggtt->mutex and ppgtt->mutex (/series/46547/)	success	New	1	Chris Wilson	None	2019-
55201	series starting with [1/3] drm/i915: Prevent concurrent GGTT update and use on Braswell (again) (/series/55201/)	warning	New	3	Chris Wilson	None	2019-
55194	series starting with [1/3] drm/i915/audio: Track temporary rpm wakerefs (/series/55194/)	warning	New	3	Chris Wilson	None	2019-
55200	series starting with [1/8] drm/i915: Serialise concurrent calls to i915_gem_set_wedged() (/series/55200/)	failure	New	8	Chris Wilson	None	2019-
48194	Per context dynamic (sub)slice power-gating (/series/48194/)	failure	New	6	Tvrtko Ursulin	None	2019-
55154	series starting with [v2,1/2] drm:	warning	New	2	Emil Velikov	None	2019-

annotate

	annotate drm_core_check_feature() dev arg. as const (/series/55154/)						
55181	series starting with [CI,01/21] drm/i915: Track all held rpm wakerefs (/series/55181/)	failure	In progress 3	21	Chris Wilson	None	2019-
55097	series starting with [v3,1/4] drm/i915/psr: Allow PSR2 to be enabled when debugfs asks (/series/55097/)	warning	New	4	Souza, Jose	None	2019-
55095	drm/i915: GTT remapping for display (/series/55095/)	failure	New	6	Ville Syrjälä	None	2019-
55083	drm/i915/cmdparser: whitelist needed predicate registers for Anv (/series/55083/)	success	New	1	Lionel Landwerlin	None	2019-
54942	drm/i915: Try to sanitize bogus DPLL state left over by broken SNB BIOSen (/series/54942/)	success	New	1	Ville Syrjälä	None	2019-
55081	Enable/disable gamma/csc dynamically and fix C8 (/series/55081/)	warning	New	13	Ville Syrjälä	None	2019-
55035	Enable Y2xx and Y4xx (xx:10/12/16 bits) packed formats for ICL (/series/55035/)	warning	New	3	Sharma, Swati2	None	2019-
54030	MST refcounting/atomic helpers cleanup (/series/54030/)	warning	New	20	Lyude Paul	None	2019-
49983	drm/i915: Infoframe precompute/check (/series/49983/)	failure	New	10	Ville Syrjälä	None	2019-
54991	series starting with [1/3] drm/i915/ringbuffer: EMIT_INVALIDATE *before* switch context (/series/54991/)	success	New	3	Chris Wilson	None	2019-
54986	series starting with [01/21] drm/i915: Track all held rpm wakerefs (/series/54986/)	failure	In progress 1	21	Chris Wilson	None	2019-
54967	series starting with [v2,1/2] drm/i915/selftests: recreate WA lists inside the selftest (/series/54967/)	warning	In progress 3	2	Daniele Ceraolo Spurio	None	2019-
54962	drm/i915: init per-engine WAs for all engines (/series/54962/)	success	New	1	Daniele Ceraolo Spurio	None	2019-
54959	drm/i915/psr: simplify enable_psr handling (/series/54959/)	failure	New	1	Ross Zwisler	None	2019-
54948	series starting with [1/2] drm/i915: Reduce recursive mutex locking from the shrinker (/series/54948/)	success	New	2	Tvrtko Ursulin	None	2019-
54896	series starting with [1/5] drm/i915/backlight: Restore backlight on resume, v3. (/series/54896/)	warning	New	5	Maarten Lankhorst	None	2019-
54903	series starting with [1/4] drm/edid: Pass connector to AVI infoframe functions (/series/54903/)	warning	New	4	Ville Syrjälä	None	2019-
54876	series starting with [1/2] drm/i915: Enable render context support for Ironlake (gen5) (/series/54876/)	failure	New	2	Chris Wilson	None	2019-
54884	series starting with [1/2] drm/i915/gvt: give the cmd	warning	New	2	Jani Nikula	None	2019-

	parser decode_info a const treatment (/series/54884/)						
54869	series starting with [1/2] drm/i915/userptr: Avoid struct_mutex recursion for mmu_invalidate_range_s (/series/54869/)	warning	New	2	Chris Wilson	None	2019-
25091	Add HDR Metadata Parsing and handling in DRM layer (/series/25091/)	warning	New	12	Shankar, Uma	None	2019-
54803	series starting with [01/46] drm/i915: Return immediately if trylock fails for direct-reclaim (/series/54803/)	failure	In progress 1	46	Chris Wilson	None	2019-
54859	drm/i915: drop all drmP.h includes (/series/54859/)	failure	New	1	Jani Nikula	None	2019-
54857	drm/i915/gvt: remove drmP.h include (/series/54857/)	success	New	1	Jani Nikula	None	2019-
54797	series starting with [1/2] drm/i915: Prevent a race during I915_GEM_MMAP ioctl with WC set (/series/54797/)	failure	New	2	Joonas Lahtinen	None	2019-
54775	drm/i915: Combined gt.awake/gt.power wakerefs (/series/54775/)	failure	New	1	Chris Wilson	None	2019-
54774	drm/i915: Simplify enabling gen6/7 user interrupts (/series/54774/)	failure	New	1	Chris Wilson	None	2019-
54768	drm/i915: Watchdog timeout: Blindly trust watchdog timeout for reset? (/series/54768/)	warning	New	1	Carlos Santa	None	2019-
54744	series starting with [v3,1/2] drm/i915: Reduce recursive mutex locking from the shrinker (/series/54744/)	success	New	2	Tvrtko Ursulin	None	2019-
54739	series starting with [1/2] drm/i915: Move workaround infrastructure code up (/series/54739/)	success	New	2	Tvrtko Ursulin	None	2019-
54692	series starting with [v2,1/6] drm/i915/psr: Allow PSR2 to be enabled when debugfs asks (/series/54692/)	failure	New	6	Souza, Jose	None	2019-
54721	drm/i915/ringbuffer: Drop gen7_xcs_emit_breadcrumb (/series/54721/)	warning	New	1	Chris Wilson	None	2019-
54684	Shrinker tweaks/fixes? (/series/54684/)	failure	New	4	Tvrtko Ursulin	None	2019-
50497	drm/i915: Always try to reset the GPU on takeover (/series/50497/)	success	New	1	Chris Wilson	None	2019-
54639	drm/i915/selftests: Take a breath during check_partial_mappings() (/series/54639/)	success	New	1	Chris Wilson	None	2019-
54636	series starting with [01/39] drm: Reorder set_property_atomic to avoid returning with an active ww_c (/series/54636/)	failure	In progress 1	39	Chris Wilson	None	2019-
54547	drm: Reorder set_property_atomic to avoid returning with an active ww_ctx (/series/54547/)	success	New	1	Chris Wilson	None	2018-
50834	CRTC background color	warning	New	3	Matt Roper	None	2018-

(/series/50834/)

	(/series/50834/)						
54529	series starting with [1/6] drm/i915: Remove redundant trailing request flush (/series/54529/)	warning	In progress 3	6	Chris Wilson	None	2018-
54523	series starting with [CI,1/2] drm/i915/execlists: Pull the render flush into breadcrumb emission (/series/54523/)	warning	In progress 1	2	Chris Wilson	None	2018-
54520	series starting with [1/3] drm/i915: Restrict PSMI context load w/a to Haswell GT1 (/series/54520/)	warning	In progress 1	3	Chris Wilson	None	2018-
54494	drm/i915: drmP.h include removal w/ drm prep work (/series/54494/)	warning	In progress 3	6	Jani Nikula	None	2018-
54518	series starting with [1/3] drm/i915: Implement Selective Write workaround for Haswell GT1 (/series/54518/)	failure	In progress 3	3	Chris Wilson	None	2018-
54517	series starting with [1/2] drm/i915: Remove HW semaphores for gen7 inter- engine synchronisation (/series/54517/)	warning	In progress 6	2	Chris Wilson	None	2018-
54499	drm/i915: modparam rework prep work (/series/54499/)	warning	In progress 1	6	Jani Nikula	None	2018-
47132	Add Colorspace connector property interface (/series/47132/)	failure	New	2	Shankar, Uma	None	2018-
54503	drm: add DRM_DEBUG_CORE() and friends and use them (/series/54503/)	warning	New	1	Jani Nikula	None	2018-
54431	Gen9 Guc and HuC Updates (/series/54431/)	failure	New	8	Anusha	None	2018-
54127	series starting with [RESEND,1/5] drm/i915/backlight: Restore backlight on resume, v2. (/series/54127/)	warning	New	5	Maarten Lankhorst	None	2018-
54424	skl+ watermark stuff (/series/54424/)	warning	New	9	Ville Syrjälä	None	2018-
54404	Move pm_runtime accounted time to raw nsec (/series/54404/)	warning	New	3	Vincent Guittot	None	2018-
54341	series starting with [1/3] drm/i915/ddi: Move DDI port detection to the corresponding helper (/series/54341/)	warning	In progress 3	3	Imre Deak	None	2018-
54364	drm/debugfs_crc: Degrade ERROR when overflowing to INFO (/series/54364/)	warning	New	1	Maarten Lankhorst	None	2018-
54414	drm/i915: from module params to device params (/series/54414/)	failure	In progress 6	11	Jani Nikula	None	2018-
38254	drm/i915: Implement HDCP2.2 (/series/38254/)	failure	New	39	Ramalingam C	None	2018-
54330	drm/i915: Fix i915_gem_wait_for_idle oops due to active_requests check (/series/54330/)	failure	New	1	Yang, Bin	None	2018-
54285	series starting with [1/9] drm/i915: Remove HW semaphores for gen7 inter- engine synchronisation	warning	In progress 3	9	Chris Wilson	None	2018-

(/series/54285/)

	(/series/54285/)						
54213	series starting with [1/3] drm/i915: Prepare for larger CSB status FIFO size (/series/54213/)	failure	New	3	Mika Kuoppala	None	2018
54238	sysfs: Disable lockdep for driver bind/unbind files (/series/54238/)	warning	New	1	Daniel Vetter	None	2018
53928	drm/i915: correct the pitch check for NV12 framebuffer (/series/53928/)	success	New	1	raviraj.p.sitaram@intel.com	None	2018
54170	series starting with [v4,1/2] drm: Add color management LUT validation helper (v4) (/series/54170/)	success	New	2	Matt Roper	None	2018
54242	series starting with [1/5] drm/i915: Remove HW semaphores for gen7 inter- engine synchronisation (/series/54242/)	warning	In progress ①	5	Chris Wilson	None	2018
54226	drm/i915: Disable FBC on fastset if necessary (/series/54226/)	warning	New	1	Maarten Lankhorst	None	2018
54222	Move pm_runtime accounted time to raw nsec (/series/54222/)	failure	New	3	Vincent Guittot	None	2018
54059	PM/pm_runtime: move on hrtimer and nsec (/series/54059/)	warning	In progress 1	3	Vincent Guittot	None	2018
54143	drm/i915: Enable fastboot by default on Skylake and newer (/series/54143/)	failure	New	1	Hans de Goede	None	2018
738	dim: Remove git commit amend from dim_apply (/series/738/)		New	1	Ander Conselvan de Oliveira	None	2018
54091	drm/i915/icl: restore WaEnableFloatBlendOptimization (/series/54091/)	failure	New	1	Talha@freedesktop.org, Nassar@freedesktop.org, talha.nassar@intel.com	None	2018
54023	Add gamma/degamma LUT validation helper (/series/54023/)	warning	New	2	Matt Roper	None	2018
54017	drm/i915/icl: Fix TypeC legacy HPD handling (/series/54017/)	warning	In progress 6	4	Imre Deak	None	2018
54070	Define MOCS table for Icelake (/series/54070/)	success	New	4	Lucas De Marchi	None	2018
54069	drm/i915/dsi: Add PORT_TX_DW7 programming to DSI vswing sequence (/series/54069/)	failure	New	1	clinton.a.taylor@intel.com	None	2018
54052	series starting with [1/4] drm/i915/backlight: Restore backlight on resume, v2. (/series/54052/)	failure	New	4	Maarten Lankhorst	None	2018
53996	drm/i915/opregion: rvda is relative from opregion base, not absolute (/series/53996/)	failure	New	1	Jani Nikula	None	2018
53980	series starting with [CI,1/4] drm/i915/selftests: Check we can recover a wedged device (/series/53980/)	failure	In progress 3	4	Chris Wilson	None	2018
53962	series starting with [1/6] drm/i915: Shrink ilk-bdw wm storage by using u16 (/series/53962/)	warning	New	6	Ville Syrjälä	None	2018
53953	series starting with [01/19] drm/i915: Return immediately if trylock fails for direct-reclaim (/series/53953/)	warning	In progress 3	19	Chris Wilson	None	2018

53948	drm/amd: Compile fix for amdgpu_dm.c (/series/53948/)	failure	New	1	Mika Kuoppala	None	2018-
53929	Add gamma/degamma LUT validation helpers (/series/53929/)	warning	New	2	Matt Roper	None	2018-
53901	series starting with [CI,1/2] drm/i915: Don't use DDB allocation when choosing gen9 watermark method (/series/53901/)	warning	New	2	Matt Roper	None	2018-
53898	series starting with [v3,1/2] drm/i915: Don't use DDB allocation when choosing gen9 watermark method (/series/53898/)	warning	New	2	Matt Roper	None	2018-

 $patchwork \ (http://jk.ozlabs.org/projects/patchwork/) \ patch \ tracking \ system \ | \ about \ patchwork \ (/help/about/)$

« 1 2 ... 46 »