
Creating Dashboards

A quick overview of creating dashboards in the XL Productivity Appliance™ v2.20 and later.

XL includes a powerful engine for custom reporting via Dashboards. Each Dashboard starts as a blank page, allowing you to add any of the following widget combinations and control the dashboard layout.

All dashboard widgets are enterprise-aware, so every widget can include data from one or more Work Centers in your hierarchy.



View Menu

The **View Menu** hosts the functions for dashboards and some reports, including the ability to assign a view as the Page or Device default.


Action	Description
Create new view	Creates a new local view. Only available on dashboard pages.
Share this view	Converts a local view to a shared view so anyone can access it, deleting the local view. You must be logged in to share a view.
Modify name of view	Allows you to change the name of the current view.
Delete this view	Deletes the current view. Not available for Built-In views
Page default	Sets the current view as the default view for this page (e.g. Dashboards or All Production). Only available for built-in and shared views, and when the view visibility is set to Anyone.
Device default	Sets the home page for the device (i.e., when the IP Address is entered). Only available for built-in and shared views, and when the page and view visibility is set to Anyone.
Access Control	Restricts selected view or page.

Save Menu

The **Save Menu** hosts the save and copy functions for dashboards.

Action	Description
Save	Saves the view in its current state.
Save As	Creates a copy of the current view as a local view with a new name.

Create a Report



1. Navigate to **Reports Menu > All Dashboards**
2. Click **View > + Create new view**.
3. Name your new Report.
4. To make dashboard shareable, ensure you are logged in as Administrator, then navigate to **View > Share this View** and click **OK to Share**.
5. If necessary, click the **Layout** control in the page control bar to change the dashboard from view mode to layout mode.
6. Click **+ Add Widget** and select from list.

Layout Mode

Each dashboard can include any number of sections, and each section can be configured using any one of eight column layouts. Each column can hold any number of stacked widgets.



Section Layout Controls:

Icon	Control	Description
	Add Section	Insert a new blank section beneath the currently selected section.
	Move Section Up	Move the currently selected section above the prior section.
	Move Section Down	Move the currently selected section below the next section.
	Delete Section	Delete the entire section.
	Column Layouts	Configure column layout within the section. Choose from eight different options with up to six columns per section.

Widget Layout Controls:

Icon	Control	Description
	Add Widget	Insert a widget in the current section.
	Delete Widget	Delete widget from the current section.
	Move Widget	Freely move widget within dashboard.


Common Controls

Below are controls consistently present in most widgets:

Icon	Control	Description
	Show Controls	Show or hide controls while in either View Mode or Layout Mode.
	Enterprise	Isolate or combine work centers within a widget.
	Time Range	Choose to follow the main page's time selector or isolate your time range to a specific widget.
	Metrics	Or Columns, typically contain quantitative metrics.
	Dimensions	Or Rows, typically contain qualitative values.
	Filters	Restrict the underlying data by creating expressions for various Metrics and Dimensions.
	Duplicate	Copy an existing widget in layout mode.

Andon

Andon widgets are beneficial for viewing up to four metrics in real-time or looking at historical data. You can show multiple Dimensions in the footer of the widget such as showing the current Job and Part. Common Controls are used to configure this widget.



Chart

Charts are useful for comparing, contrasting, and trending information for a visual audience.


Icon	Control	Description
	Chart Type	Choose from cluster, column, heat map, line, Pareto, stacked column, and stacked Pareto.
	Data Point	On time series data, the specific data value; for Pareto charts, the cumulative percentage.
	Trend Line	Shown by default for time series data.
D	**Time Units**	Change the time granularity to Hour, Shift, Day, Week, Month, Quarter, or Year.

The Chart widget includes a feature called Quick Charts that enables you to generate a chart by simply selecting metrics and dimensions in a way that resembles a chart title:



Chronogram

Chronograms are useful for visually showing category values over time.




In addition to Common Controls, choose the edit icon to configure:

Icon	Control	Description
	Add Strip	Add data that will be visualized.
	Strip Height	Make strip short or tall.
	Heat Metric	Select the metric that determines color of heat mapping.
	Text Overlay	Optionally show the dimension value and up to three metrics on chronogram events.
	Labels	Optionally show site/area/work center labels and legend.
	Strip Placement	Move Strip Up, Move Strip Down, Delete Strip

Event List

Event Lists enable you to explore production information in a vertical timeline, where time is organized by whatever production- or time-based dimension you choose and search the comments associated with your events.





In addition to Common Controls, you can configure:

Icon	Control	Description
	Heat Metric	Select the metric that determines color of heat mapping.
	Metrics	Select quantitative values in text overlay
	Event Body	Choose level of detail of information below each heading

KPI and KPI Group


KPIs provide detailed information about a single metric while KPI Groups show multiple metrics organized in tabular fashion. You can configure up to 30 metrics and formatting components with KPI Groups.






Table

Tables show tabular information either grouped with drilldown or chronologically by event.







In addition to Common Controls, you can configure:

Icon	Control	Description
	Level	Select the level of detail in rows.
	Sort	Add sort rules of column dimension(s). You can add multiple sorting rules to tables.
	Group	Organize data by individual event, aggregated, or hierarchical.
	Export	Export to Microsoft Excel® (.xlsx format).

Top Losses Table

Top Losses allows you to see your top losses within a larger dashboard page.

Rank	Top Loss	Lost Time	Occurrences	Loss Percentage	Trend
1	Performance Small Stops	0h 17m 51s	634 stops	23.7%	62.1%
2	Down No Caps	0h 15m 6s	5 events	20.1%	-15.2%
3	Performance Cycle Loss	0h 7m 39s	4,178 cycles	10.2%	287.1%
4	Changeover Disinfection	0h 6m 8s	1 event	8.1%	–
5	Changeover Swabs	0h 6m 1s	1 event	8.0%	–
6	Down Jam	0h 5m 50s	2 events	7.8%	–
7	Down Main B Bus Undervolt	0h 4m 45s	2 events	6.3%	165.8%
8	Changeover Die Exchange	0h 3m 52s	1 event	5.1%	–
9	Down Broken Conveyor	0h 3m 40s	1 event	4.9%	–
10	Quality Startup Rejects	0h 2m 16s	83 pieces	3.0%	19.7%
11	Down No Operator	0h 1m 21s	1 event	1.8%	–
12	Quality Production Rejects	0h 0m 45s	28 pieces	1.0%	-40.0%

In addition to Common Controls, you can configure:

Icon	Control	Description
	Row Options	Limit the number of rows visible.
	Sort	Add multiple sort rules (default by rank).
	Export	Export to Microsoft Excel® (.xlsx format).

Pivot Table

Pivot Tables summarize and cross-tabulate data across multiple dimensions, which makes it easier to see patterns in your data.

	Cosmetic Defect	Detected by Max WIP	Out of Spec	Overweight	Reject	Scratch	Underweight
Shift	Reject Count	Reject Count	Reject Count	Reject Count	Reject Count	Reject Count	Reject Count
First Shift	207	244	175	213	232	240	238
Second Shift	174	185	262	260	238	245	266
Third Shift	226	308	223	276	281	317	271

In addition to Common Controls, you can configure:

Icon	Control	Description
	Level	Select the level of detail in rows.
	Row	Select the qualitative values shown in rows.
	Column	Select overarching category of quantitative data in pivot table columns.
	Metric	Select quantitative data in pivot table columns.
	Export	Export to Microsoft Excel® (.xlsx format).