

DX-D 100 Wireless	SB No. 21
DX-D 100	SB No. 22
DX-D 300	SB No. 32
DX-D 400	SB No. 03
DX-D 500	SB No. 24
DX-D 600	SB No. 16
DX-D 800	SB No. 07

DD+DIS051.13E

Service Bulletin

Necessary Paint Retouches for several DX-D Solutions

Task

Timing		Category	Scope
Next service as agreed with customer	0	Apply at all sites	
	•	Apply at affected sites as listed below	PowerHelp complaint / HQ issues: HQ_1209130003, HQ_1201260002
	0	Optional to improve functionality of product	_ , _

Task Tracking

After completion of your task the following entry in your Service Report is required:

DD+DIS051.13E

* Insert the document number into the field "Comment" (SMS form).

Purpose of this document:

- This document describes the necessary steps for re-touching damages in the paint coat where paint has worn off.
- It contains the solution for the listed HQ cases.

Affected serial number(s) / batch:

The signatures on the approval page indicate the solutions described in this Service Bulletin have been reviewed and are NOT reportable because no actions are taken to reduce a "Risk to Health" according to our risk assessment process.

Use, dissemination, distribution or reproduction of this bulletin by unauthorized personnel is not permitted and may be unlawful. The controlled version of this document is available from the Agfa HealthCare Library. Any printed copy of this document is uncontrolled.

Copyright © 2013 Agfa HealthCare N.V. | Document Node ID: 39996718 | service_bulletin_template_v08

Release date: 04-2013DX-D 100 Wireless, DX-D 100, DX-D 300, DX-D 400, DX-D 500, DX-D 600, DX-D 800



Service Bulletin DD+DIS051.13E

1 Introduction/Purpose

The coat of paint on the DX-D 100 Wireless / 100 / 300 / 400 / 500 / 600 / 800 is subject to wear and tear.

Because the original correct spare paint can not be distributed world-wide due to shipping and storage limitations, it is advised to buy the appropriate paint types locally.

Symptom

The following HQ cases have been reported for the DX-D solutions mentioned above:

HQ Case Number	Description
HQ_1209130003	Poor quality of Agfa Labels on the machine; No spray paint available to fix the coat of paint if the color wears off.
HQ_1201260002	Spare color cans and official spare part numbers should be provided for retouching DX-D 100, DX-D 300, DX-D 600, DX-D 800 (DX-D 500) machine bodies if required.

Solution

These HQ cases have been solved with the measure described in this bulletin.

2 Prerequisites

RAL paint types:

White: RAL9003Grey: RAL7037



NOTE:

The RAL coding is an international standard, so these color shades will be available world-wide.



TOOLS:

N. a.

Release date: 04-2013DX-D 100 Wireless, DX-D 100, DX-D 300, DX-D 400, DX-D 500, DX-D 600, DX-D 800



Service Bulletin DD+DIS051.13E

3 Instructions



REQUIRED TIME:

N.a.

Steps:

- (1) If possible, dismount a part of the machinery and use it as a sample part.
- (2) Take it to any local paint shop.
- (3) There, have the required shade mixed from the two RAL paint types mentioned in 2.
- (4) Have the mixed paint filled into spray cans.



NOTE:

It is advised to use an acrylic-based paint (non-surface critical appliance, fast drying time, scratch-resistant).



IMPORTANT:

Make sure to observe the security hints of the paint manufacturers on the paint cans!

4 Verification

N. a.

5 Keywords

Paint; White: RAL9003; Grey: RAL7037; spray paint

6 Version history

Version	Change	Date
1.0	Initial version	04-2013

Release date: 04-2013DX-D 100 Wireless, DX-D 100, DX-D 300, DX-D 400, DX-D 500, DX-D 600, DX-D 800



Details as of PDF Creation Date

Document Metadata

Document Metadata	
Title:	DX-D 100 Wireless and other DX-D Solutions - Service Bulletin No. 21 - Paint Retouches
Livelink ID:	39996718
Version#:	6
Version Date:	2013/04/10 05:50 PM CET
Status:	Approved on 2013/04/15 02:32 PM CET
Owner:	Beate Richter (axnwp)
Created By:	Beate Richter (axnwp)
Created Date:	2013/03/12 04:06 PM CET
PDF Creation Date:	2013/04/15 05:44 PM CET

This document was approved by:

Signatures:

- 1. Josef Wagner (agwj) on 2013/04/11 10:49 AM CET
- 2. Paul Merckx (amdag) on 2013/04/11 09:22 AM CET
- 3. Bart Biesemans (amajm) on 2013/04/15 01:00 PM CET
- 4. Dimitri Hofman (amfph) on 2013/04/15 02:12 PM CET

Detailed Approver History:

Approval Workflow started on 2013/04/10 05:56 PM CET

- Approval task originally assigned to and completed by Paul Merckx (amdag) on 2013/04/11 09:22 AM CET
- Approval task originally assigned to and completed by Josef Wagner (agwj) on 2013/04/11 10:49 AM CET
- Approval task originally assigned to and completed by Dimitri Hofman (amfph) on 2013/04/15 02:12 PM CET
- Approval task originally assigned to and completed by Bart Biesemans (amajm) on 2013/04/15 01:00 PM CET

Version & Status History

Version#	Date Created	Status
6	2013/04/10 05:50 PM CET	Approved - 2013/04/15

5	2013/04/10 05:47 PM CET	
4	2013/03/27 06:00 PM CET	Reviewed - 2013/04/09
3	2013/03/27 04:28 PM CET	
2	2013/03/12 05:13 PM CET	Reviewed - 2013/03/26
1	2013/03/12 04:06 PM CET	