

Check List

Prepared By	Verified By	Approved By

C438

Order Code: TGM-62107

Software code:

Instruction : ทดสอบการทำงานของอินพุต Remote

1. Config		•					
Function	Input	Botton	Comment	Min	Max	Pass	Fail
Score A		F1		0	99		
Score B		F2		0	99		
Set A		F3		0	9		
Set B		F4		0	9		
Time		SET TIME		00:00	23:59		

Instruction : ทดสอบการทำงานของ Inpot

Function	Input	Count	Scale		Decimal	Display	Pass	Fail
		Input	High	Low	Point	Display	r ass	lait
Score A	UP	20	-	-	-	20	/	
Score A	Down	21	-	-	-	21	/	
Score B	UP	22	-	-	-	22	/	
Score B	Down	23	-	-	-	23	/	
Set A	UP	2	-	-	-	2	/	
Set A	Down	3	-	-	-	3	/	
Set B	UP	4	-	-	-	4	/	
Set B	Down	5	-	-	-	5	/	