

Check List

Prepared By	Verified By	Approved By

Order Code: TGM-62073 Software code: C435

Instruction : ทดสอบการทำงานของอินพุต Remote

1. Config		•					
Function	Input	Botton	Comment	Min	Max	Pass	Fail
Decimal		DP		0	2		
Scale High Limit		SCALE+		Scale Low	999		
Scale Low Limit		SCALE-		-199	Scale High		
ค่าชดเชย		F4		-199	999		
Address		ADD		1	255		
Parity		T BASE	4800, 9600, 19200, 38400, 57600	0	4		
Baud Rate		B/R	None Odd Even	0	2		

Instruction : ทดสอบการทำงานของ Inpot

Function	Input	Current	Sc	Scale		Display	Pass	Fail
	input	Input	High	Low	Point	Display	li ass	1 alt
Temp Tank	PT100	100R	Fix 100	Fix 0	1	0.0	/	
Temp In	PT100	110R	Fix 100	Fix 0	1	27.0	/	
Temp Out	PT100	120R	Fix 100	Fix 0	1	58.0	/	
Water Pressure	4-20mA	4 mA	200	40	1	4.0	/	
Air Pressure	4-20mA	12.34 mA	200	40	1	12.5	/	



## Check List

Prepared By	Verified By	Approved By

C435

Order Code: TGM-62073

Software code:

## Instruction : ทดสอบการทำงานของ RS485 Modbus RTU for TEMP

Function	RTU	Current			Read	Error	Pass	Eail
runction	KTO	Address	Parity	Baud Rate	Value	LITOI	1 033	1 alt
	PV In	1	None	9600	1000	0	/	
	PVS Out	1	None	9600	1000	0	/	
	SCL Tank	1	None	9600	1000	0	/	
Read								
	PV In	1	None	9600	10	10	/	
	PVS Out	1	None	9600	10	0	/	
	SCL Tank	1	None	9600	10	0	/	
Write								

## Instruction : ทดสอบการทำงานของ RS485 Modbus RTU for Pressure

Function	RTU	Current			Read	Error	Pass	Fail
	I NIO	Address	Parity	Baud Rate	Value	LITOI	1 033	1 alt
	PV Water	2	None	9600	1000	0	/	
	PVS Air	2	None	9600	1000	0	/	
Read								
	PV Water	2	None	9600	10	10	/	
	PVS Air	2	None	9600	10	0	/	
Write								