

OPERATIONS BULLETIN

www.jig.org



BULLETIN NO. 143

FILTRATION UPDATE & TN11

12/05/2022

This Bulletin is intended for providers of Into-Plane Services and gives further information on Filter Monitor Phase Out.

This Bulletin is issued to remind users of the requirements included in the new Issue 13 JIG Inspection Checklist to establish a risk-based Management of Change (MOC) plan specific to each location at which they operate to establish what actions are required to phase out Filter Monitors (FM) from their operations. It is also recommended to establish a site-specific Transition Plan (TP) containing a schedule under which FMs will be replaced.

All sites will be evaluated against the requirements of the new Issue 13 JIG Inspection Checklist with effect from 1st January 2023, or earlier if they choose to. We consequently draw Users' attention to JIG's latest Technical Newsletter #11 that announces further delays to the possible adoption of Parker Velcon's CDFX "Water Barrier" technology into the JIG Standards.

Though all stakeholders are working with the manufacturer to facilitate re-qualification to the EI1588 Specification and the further subsequent evaluation, at the time of writing it is difficult to predict with any certainty when or if the CDFX 2" element may be adopted.

We therefore recommend that Users who have not yet phased out FMs from their operations review their MOCs and Transition Plans to ensure they will be able to complete it within the time scale they set for themselves based on their own risk assessment. A copy of TN11 is attached to this bulletin.

Actions to Implement this Bulletin (See Table 2 for Action Type Codes)

Action Description	Action Type	Target Completion Date
Users shall review their FM phase out MOCs and TPs to ensure they will be able to meet their schedule.	RP=A	1/7/2022

Table 2 Action Type Codes

Action Types	JIG Bulletin Action Type Definition
JS	Change to JIG Standard – to be adopted by JV and/or Operator to continue to meet the JIG Standard(s) (JIG 1, 2, 4, EI/JIG 1530 and the JIG HSSE Management System).
RA	Required Action to implement one off verification or checks outlined in the table of actions.
RP	JIG Recommended Practice which the JV should consider adopting as its own practice
I	Issued for information purposes only.

Note (**) - If the JV agreements require any of the JIG Standards and/or any of the JIG Common Processes as the governing operational standard then adoption of changes to applicable JIG Standards and/or Common Processes should not be considered optional by the JV Board.

OPERATIONS BULLETIN

www.jig.org



Note: This document is intended for the guidance of Members of JIG and companies affiliated with Members of JIG and does not preclude the use of any other operating procedures, equipment or inspection procedures.

The information contained in this publication is subject to constant review in the light of changing government requirements and regulations. Although efforts are made to keep this information up-to-date, accurate, complete, and free from error, we make no representation, warranty or guarantee, whether express or implied, that the information is up-to-date, accurate, complete, free from error, or in compliance with applicable law and regulations. No subscriber or other reader should act on the basis of any such information without referring to applicable laws and regulations and/or without taking appropriate professional advice. None of JIG, its Members, the Companies affiliated with its Members accepts responsibility for any loss or damage, whether in contract, tort (including negligence), breach of statutory duty, or otherwise, even if foreseeable, arising under or in connection with your use, adoption or reliance on the information in this document.

You use this information at your own risk, but for the full terms and conditions concerning use of this document, please refer to <http://www.jig.org/legal-copyright/>

JIG is the owner of the copyright and all intellectual property rights in the publication. IATA uses such rights with permission from JIG.

TN #11

Filter Monitor Transition update

12/05/2022

SUMMARY

This update includes the latest information from the industry filtration field trials and summarises the reasons why JIG will not be adopting the current version of the Parker Velcon CDFX Water Barrier (2") technology into the JIG Standards.

1. FIELD TRIAL PERFORMANCE – ELEMENT INTEGRITY

As communicated in TN10 (December 2021), findings from the field trial of 2" CDFX elements led to some focus being placed on the structural integrity of the CDFX elements. Findings included:

- Inconsistencies in the adhesion of the open end caps of elements
- A change in design of the centre tube to open end cap joint, from the overlapping joint used in filter monitors, to a butt joint (the butt joint having a smaller surface area for bonding, thus being an inherently weaker joint than the overlapping joint).

Lab testing showed that a failure of the end cap to centre tube joint can allow the filtration media to distort, affecting its ability to stop contaminants passing downstream.

Despite changes to the manufacturing process, structural failures continue to occur, meaning that these changes have been unable to fully resolve the robustness and reliability of this design / construction.

The manufacturer is aware of these failures and has stated its intention to partly redesign the end cap in order to strengthen and improve the consistency of the joint. When the new design is finalised and has been produced it will require at least partial requalification to the EI 1588 Specification. If the redesign is successful, the manufacturer has advised that they will submit for requalification later this year.

2. CONSEQUENCES FOR ADOPTION INTO THE JIG STANDARDS

The failure rate observed for the CDFX 2" elements, and the potential for these failures to occur during active service represents a current level of risk that is not acceptable in the JIG Standards and therefore, JIG will not be adopting the current version of CDFX 2" into the Standards.

JIG remains committed to the technical evaluation of new technologies for the replacement of Filter Monitors (FM), and therefore does intend to conduct further evaluate a redesigned version of the CDFX 2". However, this will only be considered after it has been requalified to EI 1588.

Please note that:

- It has been confirmed that the filtration media and construction will be the same for the updated CDFX element, meaning that the service life expectations already detailed in previous Newsletters are not expected to improve.
- Diligently trialling new or updated technology to ensure that only equipment that is fit for purpose is adopted into the JIG Standards takes time. Consequently, if requalified, it could be 6-12 months after EI qualification, whilst field trials are carried out, before a decision can be made regarding adopting an updated version of 2" CDFX technology in JIG.
- This decision does not automatically prohibit the possible future adoption of the CDFX 5" and 6" elements, as we understand their structural design to be different and should not contain the same potential vulnerability described above. Please note however that the 5" and 6" variants have not yet been submitted for EI 1588 qualification.
- This newsletter may require users to revise their Management of Change plans and Transition plans that are defined in TN9 and Bulletin 132.

JOINT INSPECTION GROUP

jig.org

TECHNICAL NEWSLETTER



TN #11

Filter Monitor Transition update

12/05/2022

For further information on this subject, readers are welcome to contact JIG at filtration@jig.org or technical@jig.org

If you are a JIG Member and did not receive this Technical Newsletter directly, please check your account settings on the website by signing in and going to <https://www.jig.org/user-area/emails/> .. Alternatively, please write to info@jig.org

JOINT INSPECTION GROUP

jig.org