

Job Safety and Environmental Analysis (JSEA) and Safe Work Method Statement (SWMS) Statewide Escalator Cleaning Pty Ltd

Part 1: Project and Task Identification

Process Initiators of SWMSs are responsible for consulting the Project Supervisor, Quality WHS Manager or other persons directly in charge of the work and other personnel involved in the execution of the task (as appropriate) for input into the SWMS. Other persons may be consulted for technical advice or review of the SWMS to see that proposed measures are effective and workable. The task is to be broken up into steps. For each step, the safety hazards are identified. For each of the hazards identified, corrective action, precautions, equipment are identified to reduce the hazard. All involved in the task must review and sign this SWMS form.


Client:				
Job Site:				
Contact Name	Job Title	Phone	Mobile	Email

SWMS Initiated By Suraj Khatri	Date:	SWMS No. 1	Rev: 1	Rev Date: 26.11.2025
Supervisor Review	Date:	Work Locations/ Areas: Esc 1 & 2		
Management Review	Date:			

Description of Work to be Undertaken:	
--	--

LEVEL	CONTROL	DEFINITION
Level 1	Elimination	Controlling the Hazard at source
Level 2	Substitution	Replacing one substance or Activity with a less hazardous one
	Isolation	Separating the hazard from the person
	Engineering	Guards on machinery
Level 3	Administration	Implementing policies and procedures for safe work practices
	Personal Protective Equipment	Use of safety glasses, gloves, high visibility vest.

Hierarchy of Controls



Part 2: Worker Qualifications and Induction Record

Personal Qualifications and Experience Required To Carry Out the Works:	Duties and Responsibilities of Personnel Completing the Task:	Formal or Specialised Training or Licenses Required to Complete Work or Operate Specific Equipment:
Demonstrated competency in cleaning procedures and use of cleaning products and machinery.	Adherence to company's and the site's WH&S policies and procedures	Competency in the Safe Operating Procedure of the selected machinery
	Maintain adequate house-keeping on site	
	Reporting of any injuries / incidents to the Project Supervisor	
	Operate safely and perform daily pre-shift inspections	

**SWMS Sign Off – Your signature below indicates that you have been consulted in development of
the SWMS and accept and will implement the requirements of the SWMS and control measures**

No.	Name	Classification	Employed By	Signature	Date
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					

Part 3: Hazard Analysis, Control and Legislation Worksheet

Job Safety and Environment Analysis (JSEA)			Work Method Statement (SWMS)			
Step No.	Process Steps List the steps needed to do the job in sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify controls measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By
1	Site Orientation/ Induction					
1.1	Report to clients reception; Sign in	Entering restricted areas	HIGH	Follow posted signs and go directly to reception	LOW	All
1.2	Undertake a site inspection	Unfamiliarity with emergency procedures	HIGH	Listen and ensure you obtain information and site emergency and evacuation procedures	LOW	All
		Unawareness of site-specific hazards	HIGH	Listen and ensure you obtain information about any and all site hazards	LOW	All
		Unawareness of restricted areas	HIGH	Listen and ensure you obtain information about any restricted areas	LOW	All
		Unawareness of other operations or hazardous	MEDIUM	Listen and ensure you obtain information about	LOW	All

Job Safety and Environment Analysis (JSEA)			Work Method Statement (SWMS)			
Step No.	Process Steps List the steps needed to do the job in sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify controls measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By
		activities being undertaken on site		any other activities being undertaken on site		
1.3	Establish working zone	Public entering area. Aggression. Trips or slips.	MEDIUM	Set up safety barricades at both ends of the escalator or moving walkway.	LOW	All
2	Inspection and use of Machinery for Escalator and Travelator					
2.1	Collect machine from vehicle and take to the designated location	Muscle strain	MEDIUM	Ensure correct manual handling procedures	LOW	All
				Ensure adequate personnel is utilised to distribute the load	LOW	Operator
		General Public	MEDIUM	Isolate the escalator/ travelator by placing barriers at both the top and bottom of the escalator/ travelator	LOW	Operator
2.2	Perform pre-operational inspection on the machinery	Faulty equipment machine failure	MEDIUM	Do not operate unit that has faulty parts or	LOW	Operator

Job Safety and Environment Analysis (JSEA)			Work Method Statement (SWMS)			
Step No.	Process Steps List the steps needed to do the job in sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify controls measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By
		Crushing injuries		equipment. If a problem is found, contact supervisor to initiate repairs of any damage or abnormalities		
				Ensure Operating labels undamaged and legible	LOW	Operator
				Check all safety devices	LOW	Operator
3	Clean the Escalator and/or Travelator					
3.0	Plug in machinery	Electroconduction Electric shock	EXTREME	Ensure machinery is functional, tested, tagged and current	LOW	All
				Check electrical lead for cracks, fraying or exposed wires	LOW	Operator
				Use RCD protection	LOW	Operator
3.1	Isolate / Shutdown the escalator or moving walkway	Entrapment by moving parts	EXTREME	Ensure no jewellery or loose clothing is worn when working near the escalator	MEDIUM	All
3.2	Load machine onto escalator	Muscle strain	HIGH	Two-person lift	MEDIUM	All
3.3	Turn on escalator to raise one full step	Crushing by cleaning machine	HIGH	Activate legs and automatic wheel lock	MEDIUM	All
3.4	Operate the machinery	Muscle strain	HIGH	Do not over reach	LOW	Operator

Job Safety and Environment Analysis (JSEA)			Work Method Statement (SWMS)			
Step No.	Process Steps List the steps needed to do the job in sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify controls measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By
		Electric shock	MEDIUM	Ensure machinery is functional, tested, tagged and current	LOW	All
		Personal injury	HIGH	Ensure that you have received training in safe use of the machinery	LOW	All
		Property damage	HIGH	Ensure that you have received training in safe use of the machinery	LOW	All
		Use of escalator cleaning product	HIGH	Use in accordance with Safety Data Sheet. Use in a well ventilated area.	LOW	All
3.5	Turn off the machinery	Electrocution	EXTREME	Do not remove plug by jerking or tugging electrical leads	LOW	Operator
3.6	Reverse escalator to return cleaning machine to the ground	Crushing	HIGH	Activate legs and automatic wheel lock Follow operational procedures	MEDIUM	All
3.7	Clean the machinery	Personal Injury	LOW	Ensure unit is unplugged before cleaning	LOW	Operator
4	Escalator & Moving Walk Demarcation Painting					
4.1	Isolate escalator/moving walk when setting up	Entrapment	HIGH	Ensure escalator does not operate while setting up	MEDIUM	All

Job Safety and Environment Analysis (JSEA)			Work Method Statement (SWMS)			
Step No.	Process Steps List the steps needed to do the job in sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify controls measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By
4.2	Prepare working area for paint	Exposure to paint and fumes	LOW	Follow storage and usage in accordance with Safety Data Sheet (SDS)	LOW	All
4.3	Prepare template for spray painting new demarcation lines	Muscle strain from bending and twisting	LOW	Follow manual handling guidelines	LOW	All
4.4	Paint new demarcation lines	Muscle strain from bending and twisting. Knee strain from kneeling. Exposure to paint or fumes	LOW	Follow manual handling guidelines. Wear knee pads for comfort Follow storage and usage in accordance with Safety Data Sheet (SDS).	LOW	All
4.5	Rotate Escalator / MW until complete	Entrapment by moving parts	EXTREME	Ensure no jewellery or loose clothing is worn when working near the escalator. Ensure fingers are clear when operating escalator/MW	MEDIUM	All
5	Pack up and Return to Service					
3.5	Perform post-operational inspection on the machinery	Faulty equipment machine failure	MEDIUM	Do not operate unit that has faulty parts or equipment. If a problem is found, contact	LOW	Operator

Job Safety and Environment Analysis (JSEA)			Work Method Statement (SWMS)			
Step No.	Process Steps List the steps needed to do the job in sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify controls measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By
				supervisor to initiate repairs of any damage or abnormalities		
				Ensure Operating labels undamaged and legible	LOW	Operator
				Check all safety devices	LOW	Operator
			EXTREME	Check electrical lead for cracks, fraying or exposed wires	LOW	Operator
				Use RCD protection	LOW	Operator
3.6	Return escalator/ travelator to service	Personal injury	HIGH	Ensure that you have received training in safe use of the escalator/ travelator	LOW	All
		Property damage	HIGH	Ensure that you have received training in safe use of the escalator/ travelator	LOW	All
3.7	Take machine and equipment to vehicle	Muscle strain	MEDIUM	Ensure correct manual handling procedures	LOW	All
				Ensure adequate personnel is utilised to distribute the load	LOW	Operator

Job Safety and Environment Analysis (JSEA)			Work Method Statement (SWMS)			
Step No.	Process Steps List the steps needed to do the job in sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify controls measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By
3.8	Report to clients reception; Sign out	Exiting job site	HIGH	Follow posted signs and go directly to designated location of vehicle	LOW	All

RISK CALCULATOR		Likelihood of an incident occurring				Risk level and control actions required		
Consequence of an incident	Almost Certain	Likely	Possible	Unlikely	Rare	Risk Level		Action required to control risk
Catastrophic 5 Death/permanent disability or illness. Permanent/long-term environmental impact on eco-system, major remediation required.	EXTREME	EXTREME	HIGH	HIGH	MEDIUM	Extreme	Unacceptable	Must be given immediate senior management attention.
Major 2 Serious injury or long-term health. Serious medium-term environmental effects.	EXTREME	HIGH	HIGH	MEDIUM	MEDIUM	High	Active Management	Must have considerable management to reduce to as low as reasonably practicable (ALARP)
Moderate 3 Medical attention and several days off work. Moderate short-term effects but not affecting eco-system.	HIGH	HIGH	MEDIUM	MEDIUM	LOW	Medium	Tolerable	Risks should be managed and monitored to reduce to as low as reasonably practicable (ALARP)
Minor 2 First aid treatment required. Minor effects on biological or physical environment.	HIGH	MEDIUM	MEDIUM	LOW	LOW	Low	No Action Required	Manage and monitor with normal operational management practices
Insignificant 1 Insignificant health & safety. Limited damage to minimal area of low significance.	MEDIUM	MEDIUM	LOW	LOW	LOW			
Hierarchy of risk controls (in order of preference): 1 Elimination (most effective) → 2 Substitution → 3 Isolation → 4 Engineering means → 5 Administrative controls → 6 PPE (least effective)								

Part 4: Hazard Analysis, Control and Legislation Worksheet - Site modifications, additions or alterations

Job Safety and Environmental Analysis (JSEA)				Safe Work Method Statement (SWMS)		
Step No.	Process Steps List the steps needed to do the job in the sequence to be done.	Potential Hazard(s) Against each step list potential hazards that could cause injury when the job is done.	Risk Rating	Hazard Control Measures For each hazard, identify control measures to eliminate or minimise the risk of injury.	New Risk Rating	Action By

Reference and Detail Applicable Sections of:

☒ Legislation
 ☒ Codes of Practice
 ☒ Manufacturer or Supplier Recommendations

Work Health and Safety Regulations 2017 under the Work Health and Safety Act 2011

Hazardous Manual Tasks Code of Practice

Managing Electrical Risks in the Workplace Code of Practice

Equipment to be used for task:	Equipment and Area Safety Inspections:
Escalator and/or Travelator Machines	Electrical cords to be tested and tagged and current
Safety Data Sheet	Machinery Pre Operational Checks
	Escalator Cleaner

Mandatory Personal Protection Equipment (PPE) to carry out the activity; Long pants, long sleeved shirt, safety glasses, steel capped boots, high visibility vest, gloves, hearing protection.









Required safety signage to carry out the activity; to be placed at both the top and bottom of the escalator/ travelator landings.



Caution Tri- Panel Barrier



ELECTRICAL TAGGING COLOURS:

RED - December to February **GREEN** - March to May

BLUE - June to August **YELLOW** - September to November