SOVEREIGN POWER SYSTEMS - FIELD INSPECTION LOG

ASSET: STEAM TURBINE UNIT 4

DATE: 2026-10-15

INSPECTOR ID-7742

BEARING VIBRATION: 2.4 MM/S

EXHAUST PRESSURE: 0.08 BAR

MAINTENANCE ACTION ITEMS:

1. REPLACE HYDRAULIC FILTER HF-402 AT 12000 HOURS

2. CALIBRATE GOVERNOR SENSOR GS-12

3. RE-TORQUE CASING BOLTS TO 450 NM

OVERALL STATUS: ACCEPTABLE