Rockchip Wi-Fi Situation

1.MV8686/AR6002/RT3070在Android 4.0及RK30xx平台上，将不被支持，请做好更换的准备。
2.

WiFi Chip	WiFi Module	Band	IFACE	IEEE 802.11 Standard	BT	40MHz BW	SoftAP	P2P	WPS	EMI	MIMO	Platform	Maturity
Broadcom BCM4330	Huawei MW269	2.4GHz	SDIO	IEEE 802.11B/G/N	✓	×	✓	×	✓	✓	×	RK29	Preliminary
	Azurewave NH660												
	Samsung												
Marvell 88W8787	Azurewave AW-NH387	2.4GHz	SDIO	IEEE 802.11B/G/N	✓	×	✓	×	×	×	×	RK29	Preliminary
	Samsung SWB-M30												
	CyberTan NC024												
Broadcom BCM4329	Samsung SWL-B23	2.4GHz	SDIO	IEEE 802.11B/G/N	✓	×	✓	×	✓	✓	×	RK29	Perfect
	USI WM-BN-BM-01S												
	CyberTan NC023S												
Broadcom BCM4319	Samsung SWL-B33	2.4GHz	SDIO	IEEE 802.11B/G/N	×	✓	×	×	✓	✓	×	RK28/RK29	Very Good
	USI WM-N-BM-01												
	CyberTan WC160M												
Realtek RTL8188CUS	WM-294	2.4GHz	USB	IEEE 802.11B/G/N	×	✓	✓	×	✓	✓	×	RK28/RK29	Perfect
Atheros AR6003	Atheros AR6302 Atheros AR6003 SIP	2.4GHz	SDIO	IEEE 802.11B/G/N	×	×	✓	×	✓	×	×	RK29	Good
Ralink RT5370		2.4GHz	USB								×		
CSR											×		
Marvell 88W8686	Samsung SWL-2480	2.4GHz	SDIO	IEEE 802.11B/G	×	×	×	×	×	✓	×	RK28/RK29	Very Good
	USI WM-G-MR-09												
Ralink RT3070	Azurewave AW-NU129	2.4GHz	USB	IEEE 802.11B/G/N	×	×	×	×	×	✓	×	RK28	Good
Atheros AR6002	Atheros AR6102	2.4GHz	SDIO	IEEE 802.11B/G	×	×	×	×	×	✓	×	RK28	Good

Preliminary表示还没有规模量产过，但已经在RK平台上验证为可用。	

Wi-Fi R&D and Support Team

Name	Title	E-Mail	Response
赖永乐/Lai Yong	Team Leader	lyl@rock-chips.com	
李伯堂/Li Botang	Sr. SW Engineer	lbt@rock-chips.com	