9/15/2021

Surveilia Requirements



Ben Kennedy, Chase Westlake, Ethan Pyle, Kaden Taylor CAMOSUN COLLEGE

Reference #	Requirement	Test	Pass/Fail Criteria	Criteria Met
001	Drone has stable flight	PID testing station, on a teetering wedge	Pass if motors align parallel with workbench	Pass / Fail
002	Must fly in a 3D space autonomously	Create a boundary in the system, drone must fly randomly with control	Pass if drone moves in boundary with no conditioning	Pass / Fail
003	Must send flight data to remote console	Drone sends test data to GUI.	Pass if GUI receives 90% of data at 30 meters from router	Pass / Fail
004	Must recognize a human	Camera is pointed at random objects and humans	Pass if alert is created from viewing humans with 90% accuracy	Pass / Fail
005	Must have configurable instructions through a remote console	GUI must send test data to drone	Pass if drone receives 90% of data at 30 meters from router	Pass / Fail
006	Must have a plottable flight path	Create flight path with ArduPilot and waypoints	Pass if drone collects 100% of waypoints	Pass / Fail
007	Must go idle if outside of control range	Send drone outside of boundary	Pass if drone pauses all processes and hovers indefinitely	Pass / Fail
008	Must have automatic initialization	Initialize functions on startup	Pass if startup procedure is followed	Pass / Fail
009	Must have manual interrupt of tasks	Interrupt automated flight path with command	Pass if tasks are paused after interrupt	Pass / Fail

010	Must have battery efficiency	Drone is in a hover with all peripherals active	Pass if hovers for 59 minutes without recharging	Pass / Fail
011	Must have auto-home	Drone hovers off of pad and is ordered to home	Pass if drone lands back at designated home when commanded	Pass / Fail