1. Addition of two 8-bit numbers

```
DOSBox 0.74, Cpu speed: 3000 cycles, Frameskip 0, Program: ...
File Edit Search View Options Help
                                  C:NEX1.ASM
_MODEL SMALL
.DATA
NUM1 DB 5
NUM2 DB 6
RES DB ?
.CODE
MOV AX,@DATA
MOU DS,AX
MOV AL,NUM1
ADD AL, NUM2
MOV RES,AL
MOV AH,4CH
INT 21H
END
F1=Help
                                                        Line:1
                                                                  Col:1
```

2.Addition of 2 16-bit numbers

```
DOSBox 0.74, Cpu speed: 3000 cycles, Frameskip 0, Program: ...
 File Edit Search View Options Help
                                   C:NEXZ.ASM
<u>.</u>MODEL SMALL
.DATA
NUM1 DW 5
NUM2 DW 6
RES DW ?
.CODE
MOV AX,@DATA
MOU DS,AX
MOV AX,NUM1
ADD AX, NUM2
MOV RES, AX
MOV AH,4CH
INT 21H
END
F1=Helm
                                                Line:1 Col:1
```