

WORK ORDER & SHIFT TURNOVER LOG

Asset: P-101 Heavy Crude Transfer Pump

Date: 2026-09-06 | Shift: B

Maintenance History: Drive motor replaced during turnaround 3 days ago. No laser alignment log found.

Operator Notes: High audible hum observed near flexible disc coupling.

Lubrication: Reservoir level optimal. Oil clean and clear.