

WORK ORDER & SHIFT TURNOVER LOG

Asset: P-204 Boiler Feed Pump

Date: 2026-09-06 | Shift: B

Maintenance History: Drive-End Bearing replaced 45 days ago (SKF 6312 C3).

Operator Notes: Visual check normal; zero operational anomalies detected during walkdown.

Lubrication: 250ml Mobil SHC 626 added during routine round.