




$\theta_{err} 162^\circ \cdot \text{contact } 0.07\text{m}$




$\theta_{err} 162^\circ \cdot \text{contact } 0.06\text{m}$




$\theta_{err} 169^\circ \cdot \text{contact } 0.08\text{m}$




$\theta_{err} 104^\circ \cdot \text{contact } 0.11\text{m}$




$\theta_{err} 120^\circ \cdot \text{contact } 0.09\text{m}$




$\theta_{err} 102^\circ \cdot \text{contact } 0.08\text{m}$




$\theta_{err} 84^\circ \cdot \text{contact } 0.15\text{m}$



$\theta_{err} 37^\circ \cdot \text{contact } 0.17\text{m}$



$\theta_{err} 69^\circ \cdot \text{contact } 0.18\text{m}$



M0
not-well-aligned

M1
no-contact

M2
badly-rotated