


Formation of ice on leading edge of wing.





Ice on
streamline
wire.
(Very slow
to form if
at all.)



Ice on round wire.



Ice on end of
rounded batten.



Ice on positive pitot head, showing opening
partially closed and ice forming inside tube.

Fig.2 Sketches of ice formation on wings and wires.
(From notes and sketches made on numerous flights.)