Login

Username



Password



Login



Keyboard



Select Protocol

Device Management







Device Management

- Load Cell Calibration
- O IR Sensor Calibration
- O Chiller Set Point


Confirm

Need to define subsequent workflow for each of the item in this list





Select Protocol



Confirm










Need to show 'favorite' / frequently used protocol through separate tabs?

> Could also show 'last-used protocol' only and show rest of the list on demand




06/26/2018 Batch ID











Enter Target Volumes














Confirm volumes and start procedure Material Bag 1 Quality control bag mL Material Bag 2 Product bag 1 20 mL Product bag 2 30 mL Product bag 3 20 mL Continue >

11:16:34 06/26/2018

Batch ID

Combined screen with Product bag vol. + Input(Material bag vol.) showing confirm targets


Scan disposable kit




















Scan Material Bag1 Material Bag1 Image showing mixing trag and material bag Next >







Barcode scanned for Material Bag1 is not valid



Connect Material Input Bag 1










Confirming loading



Confirming tubing set is correctly loaded




Visuals support fluid going past air detector and back







Pumping Material Bag1 into Mixing Bag




250
Supply Pump (RPM)
Product Pump (RPM)








Cooling and Mixing


















Barcode scanned for Material Bag2 is not valid



Connect Material Input Bag2



Continue










Confirming loading

Pumping Material Bag2 into Mixing Bag












Cooling and Mixing










Confirming loading

Removing Air from Product Bags












Loading material

Loading Product Bag 2












Sealing Bags










Manually Seal Bags










Unload Bags









Run complete! Remove the disposable kit before starting new run.

Run Summary

Protocol Started

Protocol Ended

Total Run Duration

11:22AM 06/26/2018 12:02AM 06/26/2018

40 Minutes

Products

Target (mL)

Actual (mL)

QC Bag

Product Bag 1 Product Bag 2

Product Bag 3

Inputs Target (mL) Actual (mL)

Material 1

Material 2

Material 3



I have read and recorded the run summary report. Allow device reset.

New Run


11:16:34 06/26/2018

Batch ID









Pressing Alarm button on footer minimizes the Alarm screen and shows you whichever procedure screen you were when Alarm occured.