

11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

1 1-Risk

> Date Taken: 11/21/2024 Taken By: Steven Kujawski

Risk overview 7061 Springfield Hills Dr. S.



2 2-Risk

> Date Taken: 11/21/2024 Taken By: Steven Kujawski

Risk identifier 7061 Springfield Hills Dr. S.






11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

3 3-Risk

Date Taken: 11/26/2024 Taken By: Steven Kujawski

This risk is a three bedroom, two bathroom, two-story dwelling with 1560 ft.², vinyl siding, brick veneer, and 30 year laminated shingles built in 1997.



4 4-COL

Date Taken: 11/21/2024 Taken By: Steven Kujawski

Front elevation damaged area overview





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

5 5-COL

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The policyholder stated that he accidentally hit the right side of the overhead door opening, causing damage to the brick veneer, wall sheathing, wall framing, the overhead door track, and the cedar trim around the overhead door.



6 6-COL

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The policyholder stated that he accidentally hit the right side of the overhead door opening, causing damage to the brick veneer, wall sheathing, wall framing, the overhead door track, and the cedar trim around the overhead door.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

7 7-COL

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The policyholder stated that he accidentally hit the right side of the overhead door opening, causing damage to the brick veneer, wall sheathing, wall framing, the overhead door track, and the cedar trim around the overhead door.



8 8-COL

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The policyholder stated that he accidentally hit the right side of the overhead door opening, causing damage to the brick veneer, wall sheathing, wall framing, the overhead door track, and the cedar trim around the overhead door.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

9 9-Attached Garage

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.



10 10-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

11 11-Attached Garage Date Taken: 11/21/2024

Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.



12 12-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

13 13-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.



14 14-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

15 15-Attached Garage

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.



16 16-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

17 17-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The vehicle has caused damage to the brick veneer, wall sheathing, and stud framing, CMU foundation wall at the base of the wall, the overhead door track, and cedar trim around the overhead door opening.



18 18-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The cedar trim around the overhead door measures 8 inches wide.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

19 19-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

Two wireless door openers are installed over the painted cedar door.



20 20-Attached Garage
Date Taken: 11/21/2024
Taken By: Steven Kujawski

The weather stop has been damaged in this loss.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

21 21-Attached Garage Date Taken: 11/21/2024

Taken By: Steven Kujawski

The overhead door track has been damaged in this loss.



22 22-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The vehicle collision has damaged the drywall and 2 x 4 nailer that the overhead door track is fastened too.






11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

23 23-Attached Garage

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The vehicle collision has damaged the drywall and 2 x 4 nailer that the overhead door track is fastened too.



24 24-Attached Garage Date Taken: 11/21/2024

Taken By: Steven Kujawski

The vehicle collision has damaged the drywall and 2 x 4 nailer that the overhead door track is fastened too.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com


25 25-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The insulated overhead door itself appears to be undamaged by this loss.



26 26-Attached Garage
Date Taken: 11/21/2024
Taken By: Steven Kujawski

The insulated overhead door itself appears to be undamaged by this loss.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

27 27-Attached Garage

Date Taken: 11/21/2024 Taken By: Steven Kujawski

Prior damage to the bottom of the the overhead door was noted. This damage is not a result of this vehicle incident.



28 28-Attached Garage Date Taken: 11/21/2024

Taken By: Steven Kujawski

Prior damage to the bottom of the the overhead door was noted. This damage is not a result of this vehicle incident.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

29-Attached Garage Date Taken: 11/21/2024 Taken By: Steven Kujawski

> Prior damage to the bottom of the the overhead door was noted. This damage is not a result of this vehicle incident.



30-Attached Garage Date Taken: 11/21/2024 Taken By: Steven Kujawski

The overhead door measures 16 feet wide by 7 feet tall.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

31 31-Attached Garage

Date Taken: 11/21/2024 Taken By: Steven Kujawski

A flag holder and two plant hooks are installed over the painted overhead door trim.



32 32-Attached Garage Date Taken: 11/21/2024

Taken By: Steven Kujawski

A flag holder and two plant hooks are installed over the painted overhead

door trim.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

33 33-Attached Garage
Date Taken: 11/21/2024

Taken By: Steven Kujawski

The damaged section of brick measures 2'5" wide by 8'8" tall.



34 34-Attached Garage Date Taken: 11/21/2024

Taken By: Steven Kujawski

The damaged section of brick measures 2'5" wide by 8'8" tall.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

35 35-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The damaged section of brick measures 2'5" wide by 8'8" tall.



36 36-Attached Garage
 Date Taken: 11/21/2024
 Taken By: Steven Kujawski
 Detached garage interior overview





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

37 - Attached Garage Date Taken: 11/21/2024 Taken By: Steven Kujawski

The attached garage measures 21'8" wide by 19'3" deep.



38-Attached Garage Date Taken: 11/21/2024 Taken By: Steven Kujawski

The ceiling height in the attached garage measures 9'2" tall





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

39 39-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

Detached garage interior overview



40 40-Attached Garage
 Date Taken: 11/21/2024
 Taken By: Steven Kujawski
 Detached garage interior overview






11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

41 41-Attached Garage
Date Taken: 11/21/2024
Taken By: Steven Kujawski

Detached garage interior overview



42 42-Attached Garage Date Taken: 11/21/2024 Taken By: Steven Kujawski

> The drywall and 2 x 4 nailer beside the overhead door will need to be removed and replaced in order to remove and replace the wall.






11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

43 43-Attached Garage

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The drywall and 2 x 4 nailer beside the overhead door will need to be removed and replaced in order to remove and replace the wall.



44 44-Attached Garage Date Taken: 11/21/2024 Taken By: Steven Kujawski

The drywall and 2 x 4 nailer beside the overhead door will need to be removed and replaced in order to remove and replace the wall.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

45 45-Attached Garage Date Taken: 11/21/2024

Taken By: Steven Kujawski

The drywall and 2 x 4 nailer beside the overhead door will need to be removed and replaced in order to remove and replace the wall.



46 46-Attached GarageDate Taken: 11/21/2024Taken By: Steven Kujawski

The drywall and 2 x 4 nailer beside the overhead door will need to be removed and replaced in order to remove and replace the wall.





11600 E. Washington St., Unit 29098 Indianapolis, IN 46229 317-973-7676 www.elevateclaims.com

47 47-Attached Garage

Date Taken: 11/21/2024 Taken By: Steven Kujawski

The drywall and 2 x 4 nailer beside the overhead door will need to be removed and replaced in order to remove and replace the wall.

