

Soil and Site Conditions Report

Marymoor Edge Development Site | Redmond, WA 98052

Price	\$1,450,000	Area	0.48 acres
City	Redmond, WA	ZIP	98052
Zoning	residential	Listing	sale / available
Road access	Available	Water	Available
Electricity	Available	Sewer	Available

Preliminary Site Conditions

This 0.48-acre parcel should receive normal soil, drainage, and buildability review before design work.

SmartPlots flags soil diligence as especially important where septic, slope, floodplain, or retaining wall issues may affect cost.

Recommended Studies

Order a geotechnical review for bearing capacity, drainage behavior, and foundation recommendations.

Confirm septic feasibility where public sewer is not available.

Adjacent traffic patterns, bike corridor setbacks, and stormwater capacity should be reviewed during feasibility.

SmartPlots Demo Note

This document is generated from SmartPlots demo data for product demonstration, RAG ingestion, and land-discovery workflow testing.