Process Dynamics & Control

Process Dynamics & Control (CH 61016)

Class Teacher: 1. Prof Amar Nath Samanta

2. Prof Parag Deshpande

Class TA

Mr. Shubham Raj Ms. Yashaswini Thakur

Mr. Nande Pradip Sugriv Mr. Yagnesh Chainy

Class Timing

Wednesday: 10 AM to 11 AM

Thursday : 9 AM to 10 AM

Friday : 11 AM to 1 PM (PD)

Attendance

Biometric method

Institute Deregistration Rule

Process Control Syllabus

- 1. Brief Review of process model and transfer function
- Review of feedback control
- 3. Model based Control
 - a) Direct Synthesis
 - b) Internal Model Control
- 4. Control of time delay and inverse response processes
- 5. Traditional Advanced Control
 - a) Feedforward Control
 - b) Cascade Control
 - c) Ratio Control
 - d) Override Control

- Multivariable Control
 - a) Loop Interaction analysis
 - b) Design of decentralized controllers
 - c) Design of Decouplers
- 7. Model Predictive control
 - a) Unconstrained DMC
 - b) Quadratic DMC
- 8. Controller design using State-Space model
 - a) State Feedback Controller
 - b) Linear Quadratic Regulator
 - c) State Observer
- Nonlinear Control
 - a) Feedback linearizing Control
 - b) Backstepping Control
 - c) Sliding mode control

Process Control

Books:

- Process Dynamics & Control -- Seborg, Edgar, Mellichamp & Doyle
- 2. Process Control -- W Bequette
- 3. Process Dynamics, Modelling
 and Control
 B A Ogunnaike & W H Ray
- 4. Modern Control Engineering -- K Ogata

Software: Knowledge of MATLAB & Simulink required for solving problems.

Benchmark Systems to be used for the course

- Tank Level System
 - 3 tank in series
 - Quadruple Tank
- Continuous Stirred Tank Heater
- Continuous Stirred Tank Reactor system
 - Isothermal Reactor (Van de Vusse reaction)
 - Non-isothermal Reactor
 - Polymerization Reactor
- Distillation Column


MATLAB / SIMULINK model will be developed based on nonlinear model

Mathematical Model of tank level system

$$\frac{dh_1}{dt} = \frac{F_0}{A_1} - \frac{a_1}{A_1} \sqrt{2gh_1}$$

$$\frac{dh_2}{dt} = \frac{a_1}{A_2} \sqrt{2gh_1} - \frac{a_2}{A_2} \sqrt{2gh_2}$$

$$\frac{dh_3}{dt} = \frac{a_2}{A_3} \sqrt{2gh_2} - \frac{a_3}{A_3} \sqrt{2gh_3}$$



Control objective:

Control the 3^{rd} tank level by manipulating pump voltage V, where $F_0 = K V$

Add q_2 input flow on the tanks 2 and set q_2 as manipulated variable.

Which one is difficult to control?

Data for Simulation in Matlab/Simulink

$$A_1$$
, $A_3 = 28 \text{ cm}^2$ $A_2 = 32 \text{ cm}^2$ $V^s = 3 \text{ V}$
 $a_1 = 0.06725 \text{ cm}^2$ $a_2 = 0.05683 \text{ cm}^2$
 $a_3 = 0.07089 \text{ cm}^2$ K=3.14

• Transfer Function model

Define :
$$x_1 = h_1 - h_1^s$$
; $x_2 = h_2 - h_2^s$; $x_3 = h_3 - h_3^s$; $u = V - V^s$
Linearizing around steady state value h_1^s

Linearizing around steady state value
$$h_1^3$$

$$\frac{dh_1}{dt} = \frac{K}{A_1}V - \frac{a_1}{A_1}\sqrt{2g} \left[\sqrt{h_1^s} + \frac{1}{2\sqrt{h_1^s}}(h_1 - h_1^s)\right]$$

Subtracting above from steady state equation,

$$\frac{dx_1}{dt} = \frac{K}{A_1}u - \frac{a_1\sqrt{g}}{A_1\sqrt{2h_1^S}}x_1 \quad \Rightarrow \text{ Transfer function } \frac{x_1(s)}{u(s)} = \frac{K_{p_1}}{\tau_{p_1}s+1}$$

Where,
$$K_{p_1} = \frac{K}{a_1} \sqrt{\frac{2h_1^S}{g}}$$
 and $\tau_{p_1} = \frac{A_1}{a_1} \sqrt{\frac{2h_1^S}{g}}$

Similarly,


$$\frac{dx_2}{dt} = \frac{a_1}{A_2} \sqrt{\frac{g}{2h_1^S}} \ x_1 - \frac{a_2}{A_2} \sqrt{\frac{g}{2h_2^S}} \ x_2 \ \text{ and Transfer function } \frac{x_2(s)}{x_1(s)} = \frac{K_{p_2}}{\tau_{p_2} s + 1}$$

$$\frac{dx_3}{dt} = \frac{a_2}{A_3} \sqrt{\frac{g}{2h_2^s}} \ x_2 - \frac{a_3}{A_3} \sqrt{\frac{g}{2h_3^s}} \ x_3 \ \text{ and Transfer function } \frac{x_3(s)}{x_2(s)} = \frac{K_{p_3}}{\tau_{p_3} s + 1}$$

Where,
$$K_{p_j} = \frac{a_{j-1}}{a_j} \sqrt{\frac{h_j^s}{h_{j-1}^s}}$$
 and $\tau_{p_j} = \frac{A_j}{a_j} \sqrt{\frac{2h_j^s}{g}}$ for j = 2,3

So, Process Transfer function
$$G(s) = \frac{x_3(s)}{u(s)} = \frac{K_{p_1}K_{p_2}K_{p_3}}{(\tau_{p_1}s+1)(\tau_{p_2}s+1)(\tau_{p_3}s+1)}$$

Quadruple Tank problem



Quadruple Tank problem

$$\frac{dh_1}{dt} = -\frac{a_1}{A_1} \sqrt{2gh_1} + \frac{a_3}{A_1} \sqrt{2gh_3} + \frac{\gamma_1 k_1}{A_1} v_1$$

$$\frac{dh_2}{dt} = -\frac{a_2}{A_2} \sqrt{2gh_2} + \frac{a_4}{A_2} \sqrt{2gh_4} + \frac{\gamma_2 k_2}{A_2} v_2$$

$$\frac{dh_3}{dt} = -\frac{a_3}{A_3} \sqrt{2gh_3} + \frac{(1 - \gamma_2)k_2}{A_3} v_2$$

$$\frac{dh_2}{dt} = -\frac{a_4}{A_4} \sqrt{2gh_4} + \frac{(1 - \gamma_1)k_1}{A_4} v_1$$

Control Objective

Both the levels of tank1 and tank2 should be controlled by manipulating voltages to the pumps.

Data for simulation:

$$A_1$$
, $A_3 = 28 \text{ cm}^2$

$$A_2$$
, A_4 = 32 cm²

$$a_1$$
, $a_3 = 0.071$ cm²


$$a_2$$
, a_4 = 0.057 cm²

$$k_1$$
, k_2 = 3.33, 3.35

$$v_1$$
, v_2 = 3.0, 3.0

$$\gamma_1$$
, $\gamma_2 = 0.7$, 0.6

Jacketed heated stirred tank



Assumptions:

Constant hold-up in tank and jacket Constant heat capacities and densities Incompressible flow

$$\frac{dV}{dt} = F_0 - F = 0$$


$$\frac{dT}{dt} = \frac{F}{V}(T_0 - T) + \frac{UA}{\rho C_P V}(T_j - T)$$

$$\frac{dT_j}{dt} = \frac{F_j}{V_j}(T_{ji} - T_j) - \frac{UA}{\rho_j C_{Pj} V_j}(T_j - T)$$

Parameter and Steady State Values

F = 30 l/min;
$$F_j^s$$
 = 50 l/min; T_0 = 15°C; T_{Jin} = 93°C; V = 300 l; V_j = 30 l; ρC_p = 1 Kcal/K l; ρC_{pj} = 1.384 ; UA = 100 Kcal/min K; T^s = 60°C ; T_J = 73.5 °C

Continuous Stirred Tank Reactor



Assumption:

- 1. Exit Condition = Reactor Condition
- 2. Isothermal Reaction
- 3. Constant volume, i.e, $F_{in} = F_{out} = F$
- 4. Only reactant A in feed is consumed, i.e, other reactant is in large excess. No product in the feed

Continuous Stirred Tank Reactor

Constant volume : dV/dt = 0

Dynamic model

$$\bullet \frac{dC_A}{dt} = \frac{F}{V} (C_{Af} - C_A) - k_1 C_A - k_3 C_A^2$$

$$\bullet \frac{dC_B}{dt} = -\frac{F}{V}C_B + k_1C_A - k_2C_B$$

$$\bullet \, \frac{dC_C}{dt} = -\frac{F}{V} C_C + k_2 C_B$$

$$\bullet \frac{dC_D}{dt} = -\frac{F}{V}C_D + \frac{1}{2}k_3C_A^2$$


Data for the CSTR

$$V = 1 \mid$$


 $F = 78 \mid /h$
 $C_{Af} = 10 \text{ mol/l}$
 $kl = 50 \text{ h-1}$
 $k2 = 100 \text{ h-1}$
 $k3 = 10 \text{ l.mol-1.h-1}$

Since our objective is to control C_B, the reduced order model should be


Steady State plot of Van-De-Vusse Reactor




Non-Isothermal Jacketed CSTR



parameter	case 1	case 2	case 3
F/V, hr-1	1	1	1
k ₀ , hr-1	14,825*3600	9,703*3600	18,194*3600
$(-\Delta H)$, kcal/kgmol	5215	5960	8195
E, kcal/kgmol	11,843	11,843	11,843
ρcp, kcal/(m³ °C)	500	500	500
T _f , °C	25	25	25
C _{Af} , kgmol/m3	10	10	10
UA/V, kcal/(m³ °C hr)	250	150	750
T _C , °C	25	25	25



Styrene Polymerization Reactor



$$egin{array}{lll} \dot{x_1}&=rac{(F_i\,C_{ia}-F_o\,x_1)}{V}-k_d\,x_1 &x_2 ext{ Monomer Conc} \ \dot{x_3} ext{ Reactor Temp} \ \dot{x_2}&=rac{(F_m\,C_{ma}-F_o\,x_2)}{V}-k_p\,x_2\,\mathcal{R} \end{array} =rac{F_o\,(T_a-x_3)}{V}-rac{\Delta H}{\rho\,C_p}\,k_p\,x_2\,\mathcal{R} -rac{UA}{\rho\,C_p\,V}\,(x_3-x_4) \ \dot{x_4}&=rac{F_j(T_{j,in}-x_4)}{V_i}+rac{UA}{\rho\,i\,C_{ni}\,V_i}\,(x_3-x_4) \end{array}$$

$$F_o = F_i + F_m + F_s.$$

The chain concentration of growing polymer is equal to


$$\mathcal{R} = (2 f k_d x_1 / k_t)^{0.5}$$

 x_1 Initiator Conc

The dissociation, propagation and termination Rate constants follow Arrhenius law:

$$k_i = k_{i0} e^{-\frac{E_i}{RT}}$$
 for I =d, p or t

Steady State Heat Power vs Reactor Temperature



Phase Portrait

