
CPU
Recovery
RESET
SPI_NOR
DC-DC&LDO
POWER TREE
GOLDEN FINGER
M.2 KEY-B
DCXO-24Mhz
DECOUPLE CAP
Maix-II
NGFF Module
If the working voltage is higher than the tolerance voltage, the IO port will be damaged.
Open-source hardware with MaixLinux, A.I. at edge.
Sipeed Technology Co, Ltd.
Sheet: /
File: Maix-II_3101.kicad_sch
Title: Maix-II_3100(Schematic)
Size: C
Date: 2021-09-02
Rev: 1.23
KiCad E.D.A. eeschema (6.0.1)
Id: 1/1
Reversion History
Version | Date | Change Notes
1.00 | 2019-11-27 | Original publish edition.
... | ... | ...
1.23 | 2021-09-02 | Updated new download circuit & pin order of CSI/LCD connectors.